

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2026

Submitted Date:

03/22/2026

Document Number:

713401317

FIELD INSPECTION FORM

Loc ID 314785 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Saint, John		jsaint@scoutep.com	
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229570	WELL	PR	01/01/2024	OW	103-07227	F V LARSON B-22X	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type	Access	
	comment:	Access	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Sign near entrance to location	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	970-675-3700/911	
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	OTHER	
	Comment:	Repeater tower - Chainlink	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:	Chainlink/Barbed wire	
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
	Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible	
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
	Comment:	Control panel	
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
	Comment:	Repeater tower	
Corrective Action:			Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229570 Type: WELL API Number: 103-07227 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				Light compaction
		Ditches				
Compaction						Light compaction

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 03/16/2026 at approximately 14:48 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC F V LARSON #B-22X PAD at Location ID #314785 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	03/22/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401318	713401317 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7488760