

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2026

Submitted Date:

03/24/2026

Document Number:

716302070

**FIELD INSPECTION FORM**

Loc ID 307894 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
B ZECHES, GIENA		gzeches@ogrisop.com	<a href="#">All Inspections</a>
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259234	WELL	PR	12/08/2004	CBM	071-07207	HILL RANCH 35-04 V	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: OTHER

Comment: PHOTO 5: AREA OF IMPACTED SOIL NEAR WELLHEAD.  
PHOTO 6: AREA OF IMPACTED SOIL NEAR PRIME MOVER SKID.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 03/30/2026

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Progressive Cavity

# 1

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

# 5

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Corrective Action:

Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 259234 Type: WELL API Number: 071-07207 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 268842      Lat: 37.046940      Long: -104.864430

Reference Point:       Other:       Length:       Width:

**Lining:**

Liner Type:       Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Other      Fencing Condition: Inadequate

Comment: PHOTO 7: LOG FENCE AROUND PIPE IS ROTTING AND HAS FALLEN DOWN.

Corrective Action REMOVE OR REPAIR FENCE PER RULE 1002.

Date: 03/30/2026

**Netting:**

Netting Type:       Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	268842	1121953	<input type="text"/>

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      Date: 3/24/2026                      Time: 12:45                      Operator: Ogris Operating LLC.10758                      Location: HILL RANCH 35-04V                      API# 05-071-07207                      County: Las Animas County.                      While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: IMPACTED SOIL, WITH RULE 1002,(2).D, CA DATE 3/30/2026. FENCING AROUND PIT IN DISREPAIR. RULE 1002, CA DATE 3/30/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	03/24/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302071	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492173">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7492173</a>