

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/18/2026

Document Number:

707801923

**FIELD INSPECTION FORM**

Loc ID: 332714      Inspector Name: Ramsey, Scott      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 68710  
Name of Operator: PETERSON ENERGY OPERATING INC  
Address: PO BOX 2169  
City: LOVELAND      State: CO      Zip: 80539-

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dornbos, Ryan	(970) 669-7411	Ryan@PEOperating.com	
Peterson, Andy	970-669-7411	andy.peterson@petersonenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150354	UIC DISPOSAL	AC	03/04/1994		-	KNOWLTON 13	AC
222236	WELL	IJ	09/02/2010	DSPW	081-05197	KNOWLTON 13	IJ

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Wednesday 2/25/2026, I, Inspector Scott Ramsey, conducted a routine inspection/ audit at Peterson Energy Knowlton #13, at API 081-05197 in Moffatt county Colorado.  
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.  
During this inspection the following possible compliance issues were observed:  
1. Access road shows signs of erosion/ channeling.  
  
Refer to photograph of observed compliance issue.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-669-7411		
Corrective Action:		Date:	_____

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Injection well		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 150354 Type: UIC API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 222236 Type: WELL API Number: 081-05197 Status: IJ Insp. Status: IJ

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [1. Access road shows signs of erosion/ channeling.](#)

Corrective Action: **Install, maintain or repair required BMPs**

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404585671	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485294">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485294</a>
707801928	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485289</a>