

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404605661

Date Received:  
04/02/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.ENR</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>
<u>Serna, Abe</u>		<u>abe.serna@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 710500741  
Inspection Date: 02/26/2026 FIR Submit Date: 02/26/2026 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705  
Address: 1775 SHERMAN ST. #2775  
City: DENVER State: CO Zip: 80203

**LOCATION** - Location ID: 307588

Location Name: LORENCITO-634S66W Number: 3NWSW County: \_\_\_\_\_  
Qtrqtr: NWS Sec: 3 Twp: 34S Range: 66W Meridian: 6  
W  
Latitude: 37.110314 Longitude: -104.772176

**FACILITY** - API Number: 05-071- -00 Facility ID: 307588

Facility Name: LORENCITO-634S66W Number: 3NWSW  
Qtrqtr: NWS Sec: 3 Twp: 34S Range: 66W Meridian: 6  
W  
Latitude: 37.110314 Longitude: -104.772176

**CORRECTIVE ACTIONS:**

**1** CA# 211183

Corrective Action: Comply with Rule 1102.j. or Rule 1105  
24 hrs to install proper OOSLAT

Date: 03/26/2026

Response: CA COMPLETED Date of Completion: 04/01/2026

Flowlines removed per rule 1102.j/1105

Operator  
Comment:

ECMC Decision:

ECMC  
Representative:

**2** CA# 211184

Corrective Action: Install sign to comply with Rule 605.g.

Date: 04/27/2026

Response: CA COMPLETED

Date of Completion: 04/01/2026

Operator  
Comment: New signs installed per rule 605.g

ECMC Decision:

ECMC  
Representative:

**3** CA# 211185

Corrective Action: Pit Liner Compromised Comply with Rule 910.

Date: 03/02/2026

Contact area EPS.

Response: CA COMPLETED

Date of Completion: 04/01/2026

Operator  
Comment: Pit liner repaired per rule 910

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: \_\_\_\_\_

Title: Construction Technician

Date: 4/2/2026 10:39:22 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404605661	FIR RESOLUTION SUBMITTED
404605670	Pit liner repairs
404605672	Risers removed
404605673	New WDID sticker installed
404605674	New well name installed

Total Attach: 5 Files