

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2026

Submitted Date:

04/02/2026

Document Number:

715802148

FIELD INSPECTION FORM

Loc ID 317684 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239778	WELL	PR	03/01/2025	GW	123-07566	ROBERT G BURGE 1	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign faded & not legible.		
Corrective Action:	Install sign or correct sign per rule 605	Date:	04/09/2026

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	dead Vegetation needs to be removed from location		
Corrective Action:	Comply with rule 606	Date:	04/09/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	fabricated steel pipe around ancillary equipment.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type:	#		corrective date
Comment:	No change to equipment from previous FIR		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239778 Type: WELL API Number: 123-07566 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/24/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Test date 3-27-2026, piped to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 4-2-2026 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 317684 API # 05-123-07566 Well name: Robert G Burge 1 County: Weld Weather: Clear Temp: 73* Location: dry While there, I observed a wellsite, PR at the time of inspection. During this inspection the following possible compliance issues were observed: 606 housekeeping: Dead vegetation needs to be removed from location CA date 4-9-2026. 605 signs: Update sign CA date 4-9-2026 Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	04/02/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404606880	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504006
715802149	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7504004