

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2026

Submitted Date:

04/09/2026

Document Number:

714202759

FIELD INSPECTION FORM

Loc ID 476278 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476278	LOCATION	AC			-	Shaw, Michael S 1	AC

General Comment:

[This is an inspection in response to a complaint.](#)

Inspected Facilities

Facility ID: 476278 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Brittani Santistevan
 Complaint Received
 Date: 03/30/2026
 Complaint Contacted: Yes
 Date: 03/30/26 Time: 12:20PM
 Location ID #: 476278
 Inspection Document #: 714202757
 Complaint Inspection Doc: 714202759
 Complaint Document #: 200452469
 Nature of Complaint: Noise, odor
 Field Inspector Actions:
 On March 30, 2026, I Brittani Santistevan, area field inspector, was assigned a complaint received by ECMC staff in reference to Noise and Odor. The complainant stated a noise and odor was occurring outside of the complainant's home. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not discover any noise/odor described in the submitted complaint. At the time of inspection, I observed construction near the suspected oil and gas location and also near the area where the complainant was reporting the noise/odor was witnessed from. I also contacted the operator and they stated they were unaware of any upset conditions at the suspected location. Weather conditions: partly cloudy, dry ground Violations of ECMC rules unrelated to the complaint was observed at the time of the inspection. All information reviewed and site inspection information were submitted to the ECMC for further review.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12