

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 12-26 Pad

Location ID: 334702



Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas/Bald Eagle Roost Sites. Location is approximately 62 yards from Pete and Bill Creek & approximately 100 yards from the Colorado River. Section/Township/Range: 26 7S96W

Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 12-26 Pad

Location ID: 334702

137° SE
Garfield County



North West corner of location.

201° S
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.