

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type UNUSED EQUIPMENT

Comment: Pipe appears to have been removed from the location. Validated FIRR Doc #404596900. Corrective Action from FIR#718000073 is cleared.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 421287 Type: WELL API Number: 123-32873 Status: PA Insp. Status: EI

Facility ID: 488903 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: Operator continues to delay further investigation or assessment of ability to resolve remediation project 33857. Operator has not submitted a Supplemental Form 27 or contacted ECMC to move Remediation Project 33857 toward closure. Corrective Action remains open.

Corrective Action: Operator to contact EPS to move Remediation 33857 toward closure Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404617333	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7512542