

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404622202

Date Received:
04/23/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 9 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Enforcement, ECMC		dnr_cogccenforcement@state.co.us
Gale, Tony	(303) 886-8733	tony@kt-res.com
Adams, Karen	(303) 886-8733	adams@kt-res.com
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov

ECMC INSPECTION SUMMARY:

FIR Document Number: 715501129

Inspection Date: 01/09/2025

FIR Submit Date: 01/09/2025

FIR Status: _____

Inspected Operator Information:

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 316154

Location Name: ANT HILL UNIT-62N96W Number: 30SESW County: RIO BLANCO

Qtrqtr: SESW Sec: 30 Twp: 2N Range: 96W Meridian: 6

Latitude: 40.108073 Longitude: -108.209844

FACILITY - API Number: 05-103-00 Facility ID: 232248

Facility Name: ANT HILL UNIT Number: 30-42

Qtrqtr: SESW Sec: 30 Twp: 2N Range: 96W Meridian: 6

Latitude: 40.108073 Longitude: -108.209844

CORRECTIVE ACTIONS:

1 CA# 201605

Corrective Action: Install liner material to ensure spill or released materials will be maintained within containment structure.

Date: 02/07/2024

Response: CA COMPLETED

Date of Completion: 04/09/2026

Operator Comment: Welder reinforced metal berm to ensure spill or released materials will be maintained within containment structure. See attached photolog.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 201608

Corrective Action: The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.

Date: 03/11/2024

Response: CA COMPLETED Date of Completion: 04/09/2026

Operator Comment: The operator has updated the well sign. See attached photolog.

ECMC Decision: _____

ECMC Representative: _____

7 CA# 201611

Corrective Action: The Location Entrance sign will identify: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available).

Date: 03/11/2024

Response: CA COMPLETED Date of Completion: 04/09/2026

Operator Comment: The information on the tank signs include all data required by the ECMC. See attached photolog.

ECMC Decision: _____

ECMC Representative: _____

8 CA# 201612

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 02/17/2024

Response: CA COMPLETED Date of Completion: 02/17/2026

Operator Comment: Operator submitted a mechanical integrity test variance request (docket # 260200036) on 2/17/2026.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment:



I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specilaist

Date: 4/23/2026 4:00:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404622202	FIR RESOLUTION SUBMITTED
404622208	Photos of completed corrective actions

Total Attach: 2 Files