

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404645715

Date Received:
05/04/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 7 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10734
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC
Address: 3838 OAK LAWN AVE SUITE 750
City: DALLAS State: TX Zip: 75219
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____
Additional Operator Contact:
Contact Name Phone Email
Archuleta, Amy aarchuleta@highriverllc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100355
Inspection Date: 04/23/2026 FIR Submit Date: 04/27/2026 FIR Status: _____

Inspected Operator Information:

Company Name: HIGH RIVER RESOURCES OPERATING LLC Company Number: 10734
Address: 3838 OAK LAWN AVE SUITE 750
City: DALLAS State: TX Zip: 75219

LOCATION - Location ID: 333517

Location Name: BONDAD 34-10-M34N10W Number: 36NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144740 Longitude: -107.881780

FACILITY - API Number: 05-067-00 Facility ID: 214279

Facility Name: BONDAD 34-10 Number: 1-36
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M
Latitude: 37.144740 Longitude: -107.881780

CORRECTIVE ACTIONS:

2 CA# 212446
Corrective Action: Cleanup stained material and dispose in approved facility and review self inspection processes to comply with 1002.f.(2).D Date: 05/04/2026
Response: CA COMPLETED Date of Completion: 04/30/2026
Operator Comment: This corrective action is complete.

ECMC Decision: _____

ECMC Representative: _____

7 CA# 212451

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Repair wildlife protection equipment (repair and close curtains) and prevent any unauthorized discharge of lube oil/antifreeze (increase spill response measures) to comply with 902.b

Date: 05/12/2026

Response: CA COMPLETED

Date of Completion: 04/30/2026

Operator Comment: This corrective action is complete.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #2 and #7 have been resolved,

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: _____

Title: Regulatory Manager

Date: 5/4/2026 2:36:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404645730	Documentation of stained soil clean up,

Total Attach: 1 Files