

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404646671

Date Received:  
05/05/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com
Gale, Tony	(303) 886-8733	tony@kt-res.com
Adams, Karen	(303) 886-8733	adams@kt-res.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 702501738

Inspection Date: 08/15/2023

FIR Submit Date: 08/16/2023

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

**LOCATION - Location ID: 316253**

Location Name: WRD FEDERAL-62N97W Number: 25SESW County: RIO BLANCO

Qtrqtr: SESW Sec: 25 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.107689 Longitude: -108.229161

**FACILITY - API Number: 05-103-00 Facility ID: 259580**

Facility Name: WRD FEDERAL Number: 25-42

Qtrqtr: SESW Sec: 25 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.107689 Longitude: -108.229161

**CORRECTIVE ACTIONS:**

1 CA# 178671

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 08/31/2023

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator Comment: Per inspection 715501355 at this location, dated 3/3/2025, this corrective action has been resolved.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 178672

Corrective Action:  Date: 08/31/2023

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator Comment:

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 178673

Corrective Action:  Date: 08/23/2023

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator Comment:

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 178674

Corrective Action:  Date: 08/23/2023

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator Comment:

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 178675

Corrective Action:  Date: 08/26/2023

Response: CA COMPLETED

Date of Completion: 09/25/2025

Operator Comment:

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 08/31/2023

Response: CA COMPLETED

Date of Completion: 03/03/2025

Operator Comment: Per inspection 715501355 at this location, dated 3/3/2025, this corrective action has been resolved.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 5/5/2026 10:01:34 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404646671	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files