

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404650952

Date Received:
05/07/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Huntington, Heather</u>		<u>hhuntington@enduringresources.com</u>
<u>Blair, Jamie</u>		<u>jamie.blair@state.co.us</u>
<u>Walter, Kyle</u>		<u>kwalter@enduringresources.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100367
Inspection Date: 04/28/2026 FIR Submit Date: 04/30/2026 FIR Status: _____

Inspected Operator Information:

Company Name: ENDURING RESOURCES LLC Company Number: 10663
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326200

Location Name: INDIAN CREEK WHEELER- M34N10W Number: 12SWSE County: LA PLATA
Qtrqr: SWSE Sec: 12 Twp: 34N Range: 10W Meridian: M
Latitude: 37.201295 Longitude: -107.884072

FACILITY - API Number: 05-067-00 Facility ID: 216030

Facility Name: INDIAN CREEK WHEELER Number: 12U-1
Qtrqr: SWSE Sec: 12 Twp: 34N Range: 10W Meridian: M
Latitude: 37.201295 Longitude: -107.884072

CORRECTIVE ACTIONS:

1 CA# 212585

Corrective Action: Install proper guy line markers per Rule 1003.a Date: 05/15/2026

Response: CA COMPLETED Date of Completion: 05/06/2026

Operator Comment: See attached pictures

ECMC Decision: _____

ECMC Representative: _____

2 CA# 212586

Corrective Action: Properly display operator name on well sign to comply with 605. Date: 06/01/2026

Response: CA COMPLETED Date of Completion: 05/06/2026

Operator Comment: see attached pictures

ECMC Decision: _____

ECMC Representative: _____

3 CA# 212587

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Date: 05/07/2026

Response: CA COMPLETED Date of Completion: 05/06/2026

Operator Comment: See attached pictures

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington Signed: _____

Title: Regulatory Specialist Date: 5/7/2026 2:36:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404650952	FIR RESOLUTION SUBMITTED
404650972	CA PHOTOS

Total Attach: 2 Files