

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 50-9 Pad

Location ID: 323863



Photo # 7026 From entrance to location



Photo # 7027 Battery sign

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 50-9 Pad

Location ID: 323863



May 7, 2026 at 3:13:39 PM
+39.455071, -108.110550
326° NW
Garfield County

Photo # 7030 Location



May 7, 2026 at 3:16:19 PM
+39.455348, -108.110498
349° N
Garfield County

Photo # 7031 Tank capacity faded & becoming illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 50-9 Pad

Location ID: 323863



Photo # 7032 Scout Card record coordinates for the FEDERAL MV 50-9 well - Coordinates appear to be off by approximately 75 ft (coordinates incorrect/not in compliance with CECMC Rules 216 & 414 – records require updating)

Photo # 7033 Scout Card record coordinates for the FEDERAL MV 50-9 well - Coordinates appear to be off by approximately 75 ft (coordinates incorrect/not in compliance with CECMC Rules 216 & 414 – records require updating)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 50-9 Pad

Location ID: 323863



Photo # 7034 Unused equipment