

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2026

Submitted Date:

05/07/2026

Document Number:

719001961

FIELD INSPECTION FORM

Loc ID: 333123 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216236	WELL	PR	03/01/2001	CBM	067-07842	KNIGHT B 1	PR

General Comment:

Inspection Report Summary
On 5/7/26 I Inspector Charles Garcia conducted an on-site inspection.
Location: KNIGHT B 1
Operator: Simcoe LLC
API#: 067-07842
County: LaPlata
All prior CA's still stand

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	WELL SIGN SIMCO STICKER IS DAMAGED HAS BP AMERICA		
Corrective Action:	Install sign or correct sign per rule 605		Date: 05/10/2026
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
Type: Other			# 1
Comment:			WELLHEAD
Corrective Action:			Date:
Type: Prime Mover			# 1
Comment:			GAS
Corrective Action:			Date:
Type: Vertical Heated Separator			# 1
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment			# 3
Comment:			2 TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION
Corrective Action:			Date:
Type: Pump Jack			# 1
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 216236 Type: WELL API Number: 067-07842 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
WELL SIGN SIMCO STICKER IS DAMAGED HAS BP AMERICA Install sign or correct sign per rule 605	garciacr1	05/07/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404651499	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7542670
719001962	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7542669