

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2026

Submitted Date:

05/11/2026

Document Number:

713401404

**FIELD INSPECTION FORM**

Loc ID: 315114    Inspector Name: Popejoy, Dusty    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
 Address: 734 MAIN STREET 3RD FLOOR  
 City: GRAND JUNCTION    State: CO    Zip: 81501

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230276	WELL	SI	05/01/2024	OW	103-07935	GOVERNMENT 6-2X	SI

**General Comment:**

This is a Field Inspection/audit of the scout card, related documents and the location.  
 Operator unable to conduct MIT testing at specified date & time.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Rig signs		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	970-693-6021/911		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment:   
 Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Workover Rig and all associated equipment		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230276 Type: WELL API Number: 103-07935 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Refer to FORM 42 document numbers 404646321 & 404646326  
On 05/11/2026 at approximately 8:00 hours arrived on location to witness scheduled MIT test, spoke with consultant Mike Shenk, who informed me the operator was not prepared to conduct the test at the scheduled date & time.

Corrective Action: **If operator is unable to conduct testing at specified date & time contact ECMC.** Date: 05/14/2026

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection/Audit Report Summary</b></p> <p>On 05/11/2026 at approximately 8:00 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP GOVERNMENT #6-2X at Location ID #315114 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed workover operations on GOVERNMENT #6-2X well.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Inspected Facilities - Operator unable to conduct MIT testing at specified date &amp; time with a CA date of 05/14/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	05/11/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404655004	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545737">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545737</a>
713401405	713401404 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545736</a>