

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404664992

Date Received:  
05/19/2026

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:  
 2 of 2 CAs from the FIR responded to on this Form  
 2 CA Completed  
 0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: <u>83130</u>	Contact Name and Telephone:
Name of Operator: <u>STRACHAN EXPLORATION INC</u>	Name: _____
Address: <u>992 S 4TH AVE SUITE 100-461</u>	Phone: ( ) _____ Fax: ( ) _____
City: <u>BRIGHTON</u> State: <u>CO</u> Zip: <u>80601</u>	Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Hayden Wambach</u>	<u>3035140757</u>	<u>haydenw@taenergy.com</u>

### ECMC INSPECTION SUMMARY:

FIR Document Number: 720800454  
 Inspection Date: 05/08/2026 FIR Submit Date: 05/11/2026 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130  
 Address: 992 S 4TH AVE SUITE 100-461  
 City: BRIGHTON State: CO Zip: 80601

### LOCATION - Location ID: 331151

Location Name: FEDERAL TOUCAN-68N60W Number: 28SESW County: WELD  
 Qtrqtr: SESW Sec: 28 Twp: 8N Range: 60W Meridian: 6  
 Latitude: 40.627650 Longitude: -104.099655

### FACILITY - API Number: 05-123-00 Facility ID: 258930

Facility Name: FEDERAL TOUCAN Number: 28-14  
 Qtrqtr: SESW Sec: 28 Twp: 8N Range: 60W Meridian: 6  
 Latitude: 40.627650 Longitude: -104.099655

### CORRECTIVE ACTIONS:

<b>1</b>	CA# <u>212821</u>
Corrective Action:	<u>Comply with Rule 606</u> Date: <u>05/29/2026</u>
Response:	<u>CA COMPLETED</u> Date of Completion: <u>05/13/2026</u>
Operator Comment:	<u>Tumbleweeds removed</u>
ECMC Decision:	_____

ECMC  
Representative:

2 CA# 212822

Corrective Action: Operator shall immediately install, repair and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b.(5)B.i and ECMC Guidance 913.b.(5)B i-v which requires fencing used be appropriate to site conditions, ie: nearby residences, depth of excavation, presence of ground or surface water, livestock, wind, etc.

Date: 05/29/2026

Response: CA COMPLETED

Date of Completion: 05/13/2026

Operator  
Comment: Fence repaired

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All CA's completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Hayden Wambach

Signed: \_\_\_\_\_

Title: Consultant

Date: 5/19/2026 8:48:33 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404664993	Fence Repair
-----------	--------------

Total Attach: 1 Files