

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/18/2026

Document Number:

714300393

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10600
Name of Operator: ANADARKO WATTENBERG OIL COMPLEX LLC
Address: 1099 18TH STREET #1800
City: DENVER State: CO Zip: 80202-

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------|---------|
| Sam LaRue | | sam.larue@westernmidstream.com | |
| Alyssa Beard | | Alyssa.Beard@westernmidstream.com | |
| , | | cogccinspections@westernmidstream.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-----------------------|-------------|
| 493868 | SPILL OR RELEASE | AC | 04/27/2026 | | - | 16-16-1420-4 Launcher | EI |

General Comment:

This is an environmental inspection to determine progress on Spill ID 493868. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions

Inspected Facilities

Facility ID: 493868 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: All excavations on location have been backfilled; no impacted soil visible.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19± Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Date: 07/13/2026

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

| Type | Management | Condition | GPS (Lat) | (Long) | |
|------|--|-----------|-----------|--------|-------------|
| | | | | | |
| | Comment No E&P waste stored on location. | | | | |
| | Corrective Action | | | | Date: _____ |

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404662886 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551735 |
| 714300394 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551726 |