



02084331

Spill 1733053

**KEY ENERGY/WILLIAMS FIELD SERVICES  
SPILL CLEANUP NEAR THE IGNACIO GAS PLANT  
CLIENT NO. 03141-034**



Photo 1: Initial spill area near plant



Photo 2: Intersection of CR 307 and Hwy 172

**KEY ENERGY/WILLIAMS FIELD SERVICES  
SPILL CLEANUP NEAR THE IGNACIO GAS PLANT  
CLIENT NO. 03141-034**



Photo 5: Oil absorbent crystals placed at intersection of CR 407 and Hwy 172



Photo 6: Final photos of intersection of CR 310 and US Hwy 550 on May 16



**KEY ENERGY/WILLIAMS FIELD SERVICES  
SPILL CLEANUP NEAR THE IGNACIO GAS PLANT  
CLIENT NO. 03141-034**



Photo 3: Pressure washing intersection of CR 307 and Hwy 172



Photo 4: Spreading sand over impacted area on CR 307

**KEY ENERGY/WILLIAMS FIELD SERVICES  
SPILL CLEANUP NEAR THE IGNACIO GAS PLANT  
CLIENT NO. 03141-034**



Photo 7: Final photos of intersection of CR 307 and Hwy 172 on May 16



Photo 8: Final photos of intersection of CR 207 on May 16