


Spill 200064273




Photograph 1 – Origin of release. The two valves in the foreground froze and ruptured. Photo is looking to the east.



Photograph 2 – Containment Ring full of CBM water looking west.




Photograph 9 – SSFENCE soil sample location.




Photograph 10 – SCULV soil sample location looking to the southwest.



Photograph 7 – DDOWN Sample location.



Photograph 8– SPAD soil sample location.




Photograph 5 – Point where culvert releases to unnamed drainage. Photo taken looking to the southeast.



Photograph 6 – DBKG Sample location looking to the west. The B26E well pad is in the background.



Photograph 3 – Containment ring full of CBM water looking to the north.



Photograph 4 – Photo looking southwest at the B26E well pad. Photo taken from culvert looking back at the silt fences and production water tanks.



Photograph 11 – SBKG soil sample location looking to the east.