



**KERR-McGEE ROCKY MOUNTAIN CORPORATION**

1999 BROADWAY, SUITE 3700 • DENVER, COLORADO 80202



December 9, 2005

PHONE: 303-296-3600  
FAX: 303-296-3601

Mr. Randall Ferguson  
Environmental Protection Specialist  
Colorado Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801  
Denver, Colorado 80203

**RE: Cullen Odenbaugh C UT #1 & Stanley Odenbaugh 13-12 Form 19**

Dear Mr. Ferguson:

Kerr-McGee Rocky Mountain Corporation (KM) is pleased to provide you with the Form 19 for the above referenced site.

Please note that following replacement of the water sump, the site was backfilled using the excavated soil rather than following the standard procedure of using clean imported fill. Due to this oversight, KM proposes to collect soil samples from the backfilled area at various depths in order to confirm that the potentially petroleum hydrocarbon-impacted soils that were replaced are below the Colorado Oil and Gas Conservation Commission (COGCC) Total Petroleum Hydrocarbons (TPH) allowable level of 1,000 milligrams per kilogram (mg/kg). Approximately five soil samples will be collected from locations around the water sump at depths ranging from two feet below ground surface (bgs) to four feet bgs. The samples will be submitted for TPH analysis by EPA Method 8015M Total Hydrocarbon Chain and the results will be included in a Form 27 along with the monitor well installation information.

Please contact me at (720) 264-2715 if you have any questions regarding the attached Form 19.

Very truly yours,

**KERR-McGEE ROCKY MOUNTAIN CORPORATION**

Paul D. Schneider, P.G.  
Environmental Coordinator

Attachments