

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or wilful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set forth in our current price schedule.

Comments

Well Directions:
Guiness left at the gravel pit, right across third creek, stay straight up Healy hill, at bottom at 4-way stop, left, this gate (5000). first right, first left towards the Croc, first left to location well on left hand side.





Calibration Report

Database File triumph.db
Dataset Pathname pass1
Dataset Creation Wed Apr 04 10:58:34 2007 by Logs Open Caved (MYLG)

Induction Tool Calibration Report

Serial Number	1119		
Calibrator Serial Number	1		
Electronic Cal Performed	Fri Mar 16 07:46:10 2007		
Surface Cal Performed	Fri Mar 16 07:46:10 2007		
Downhole Functions Performed			
Surface Calibration		Internal Cal	
Conductivity, Reference	0.000	1,000	
Conductivity, Reading	0.000	500.000	mmho
Internal Reference	0.000	1.00	
Conductivity, Reference	0.000	500.000	mmho
Conductivity, Reading	0.000	1.00	
Downhole Calibration		Internal Cal	
Conductivity, Reference	0.080	500.048	mmho
Conductivity, Reading	0.080	500.000	
Short Normal Reference	0.000	17.000	Ohm-m
Short Normal Reading	0.000	0.162	
Results		Gain	Offset
Loop Conductivity		1.000	0.000
Downhole Correction		1.000	0.140
Short Normal Resistivity		1.000	0.000

Compensated Density Calibration Report

Serial Number	2319		
Source / Verifier			
Electronic Calibration Performed	Thu Mar 08 14:44:34 2007		
Master Calibration			
	Density	Pe Detector	Hole Diameter
Magnesium	2.700 gm/cc	188.04	985.05 cts
Aluminum	2.710 gm/cc	183.00	1,000.00 cts
	Spine Angle = 76.32	Density/Spine Ratio = 0.979	
	Nps	Reading	
Small Ring	1.62 in	0.00	in
Large Ring	14.00 in	0.00	in

Gamma Ray Calibration Report

Serial Number	2321
Last Shop Performed	2321
	Wed Mar 28 14:54:21 2007
Calibrator Value	7.0 GAPI
Background Reading	0.0 GAPI
Calibrator Reading	7.0 GAPI
Sensitivity	0.2165 GAPI/cps

Sensor	Run #	Schematic	Description	Len (ft)	OD (in)	Wt (lb)
			Hang	6.75	1.50	0.00
GR	29.04		TAP-CM (2307)	7.50	5.25	40.00
			CDL-pulse (2199)	9.79	4.50	279.00
LSD	17.44					
SSD	17.44					
DSD	17.10					
DAC	6.80		HEL-D (1145)	15.25	4.50	178.00
SP	5.50					
BS	1.00					

Cablehead Tool Length 29.29 ft
Total Tool Length 29.29 ft
Triumph db Nettlesthorpe Dataset