

## Reference Photos

### North

Date Photographed: 06/18/2010

Photographed By : S. Vernon

NAD 83 - Decimal Degrees

Latitude : 39.901267

Longitude : 108.227662



### East

Date Photographed: 06/18/2010

Photographed By : S. Vernon

NAD 83 - Decimal Degrees

Latitude : 39.901267

Longitude : 108.227662



**Tri State  
Land Surveying, Inc.**

180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501  
F: (435) 781-2518

DRAWN BY: JAS

DATE: 07-15-2010

## ExxonMobil Oil Corporation

Piceance Creek Unit 297-1A  
SEC. 1, T2S, R97W, 6th P.M.  
Rio Blanco County, CO.

COLOR PHOTOGRAPHS

SHEET

**R1**



## Reference Photos

### South

Date Photographed: 06/18/2010

Photographed By : S. Vernon

NAD 83 - Decimal Degrees

Latitude : 39.901267

Longitude : 108.227662



### West

Date Photographed: 06/18/2010

Photographed By : S. Vernon

NAD 83 - Decimal Degrees

Latitude : 39.901267

Longitude : 108.227662



**Tri State  
Land Surveying, Inc.**

180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501  
F: (435) 781-2518

DRAWN BY: JAS

DATE: 07-152010

## ExxonMobil Oil Corporation

Piceance Creek Unit 297-1A  
SEC. 1, T2S, R97W, 6th P.M.  
Rio Blanco County, CO.

COLOR PHOTOGRAPHS

SHEET

**R2**