

BBC Epperly ROW Pipeline Release Photo Log

COGCC site visit – L. Spry O'Rourke and S. Baramound
Photos taken while walking northward along release
path

10/12/2010



Patched pipeline 10/12/2010
IMG_0857



Excavation soils pile IMG_0858



View to W uphill towards pipeline
release location IMG_0859



View to N from intersection of spill downhill path and ravine
that channeled it north IMG_0860



Paraffin-like material on surface (blackish in foreground)
IMG_0861



View NW from fenceline, looking at wetted channel in ravine
IMG_0862



View N from fenceline showing wetted channel,IMG_0863



View S from road crossing
located N of fenceline IMG_0864



View N from roadway N of fenceline
showing wetted channel IMG_0865



View SW of channel showing wetted area IMG_0866



View N showing wetted channel IMG_0867



View W across channel at point with narrow wetted area
IMG_0868



View to S, up channel showing wetted area. Orange X at photo bottom marks sampling location IMG_0869



View N showing sampling location IMG_0870



View N showing sampling location IMG_0871



View S showing soil sampling location beyond wetted area (orange paint) IMG_0872



Earthen dam located past end of visual wetted release
channel IMG_0873