

FORM
5A

Rev
02/08

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400109281

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571

4. Contact Name: Joan Proulx

2. Name of Operator: OXY USA WTP LP

Phone: (970) 263.3641

3. Address: P O BOX 27757

Fax: (970) 263.3694

City: HOUSTON State: TX Zip: 77227

5. API Number 05-045-14445-00

6. County: GARFIELD

7. Well Name: CASCADE CREEK

Well Number: 697-09-52B

8. Location: QtrQtr: SWSE Section: 9 Township: 6S Range: 97W Meridian: 6

9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO

Status: PRODUCING

Treatment Date: _____

Date of First Production this formation: 09/24/2009

Perforations Top: 6826 Bottom: 8422 No. Holes: 108 Hole size: 036/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

4 stages of slickwater frac with 14,326 bbls of frac fluid and 467,880 lbs of 30/50 Ottawa white sand proppant

This formation is commingled with another formation: ☐ Yes ☒ No

Test Information:

Date: 11/19/2007 Hours: 24 Bbls oil: 0 Mcf Gas: 1245 Bbls H2O: 0

Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 1245 Bbls H2O: 0 GOR: 0

Test Method: Flowing Casing PSI: 1195 Tubing PSI: 0 Choke Size: 016/64

Gas Disposition: SOLD Gas Type: DRY BTU Gas: 1087 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 7269 Tbg setting date: 11/01/2010 Packer Depth: _____

Reason for Non-Production:

Date formation Abandoned: _____ Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt _____

Bridge Plug Depth: _____ Sacks cement on top: _____

Comment:

From 10/20/2010 to 11/11/2010 work was done on the 697-09-52B well to clean out and inspect and repair the tubing. During these operations the tubing became stuck and was unable to be removed. The top of the fish is at 7518'.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 11/17/2010 Email joan_proulx@oxy.com
:

Attachment Check List

Att Doc Num	Name
400109281	FORM 5A SUBMITTED
400109291	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)