

FORM
5A
Rev
02/08

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:
400109527

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571 4. Contact Name: Joan Proulx
2. Name of Operator: OXY USA WTP LP Phone: (970) 263.3641
3. Address: P O BOX 27757 Fax: (970) 263.3694
City: HOUSTON State: TX Zip: 77227

5. API Number 05-045-16017-00 6. County: GARFIELD
7. Well Name: CASCADE CREEK Well Number: 697-16-05
8. Location: QtrQtr: SWSE Section: 9 Township: 6S Range: 97W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK Status: PRODUCING

Treatment Date: 04/14/2010 Date of First Production this formation: 04/21/2010

Perforations Top: 7389 Bottom: 7817 No. Holes: 45 Hole size: 037/100

Provide a brief summary of the formation treatment: Open Hole:

2 stages of slickwater frac with 5,669 bbls of frac fluid and 217,275 lbs of 30/50 white sand proppant

This formation is commingled with another formation: Yes No

Test Information:

Date: 05/11/2010 Hours: 24 Bbls oil: 0 Mcf Gas: 665 Bbls H2O: 73

Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 665 Bbls H2O: 73 GOR: 0

Test Method: Flowing Casing PSI: 750 Tubing PSI: 500 Choke Size: 018/64

Gas Disposition: SOLD Gas Type: DRY BTU Gas: 718 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 7658 Tbg setting date: 11/04/2010 Packer Depth: _____

Reason for Non-Production:

Date formation Abandoned: _____ Squeeze: Yes No If yes, number of sacks cmt _____

Bridge Plug Depth: _____ Sacks cement on top: _____

Comment:

Workover procedures were done on the 697-16-05 well from 11/3/2010 to 11/11/2010 to clean out, and inspect and repair the tubing. Tubing was re-landed at 7658'. The bradenhead reading on 11/17/2010 was 25 psi.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 11/17/2010 Email joan_proulx@oxy.com
:

Attachment Check List

Att Doc Num	Name
400109527	FORM 5A SUBMITTED
400109568	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)