

Hydrology for Brooks 23-22

X 7622

THERE ARE NO HYDROLOGICAL FEATURES WITHIN 1000' OF PROPOSED WELL SITE.

Graham


22

Brooks 23-22

1000'

NOTE:

FOOTAGES GIVEN ARE ONLY ESTIMATES BASED ON SUBDIVISION PLATS AND TIED TO EXISTING CONTROL. A FULL BOUNDARY SURVEY IS REQUIRED TO DETERMINE TRUE SUBDIVISION LOT AND ROAD LOCATIONS, DISTANCES AND AREA OR FOOTAGE CALCULATIONS.



Date: April 28, 2011

SHIELDS SURVEY Ltd. Co.

619 South 2nd Street

P.O. Box 639

Raton, New Mexico 87740

Phone: 445-1232 Fax: 445-3648