



**IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.**

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	24	18		0	60	100	0	60	VISU
SURF	14+3/4	9+5/8		0	2,766	1,825	0	2,766	VISU
1ST	7+7/8	4+1/2		0	9,491	768	5,120	9,491	CBL

ADDITIONAL CEMENT

Cement work date: \_\_\_\_\_

Details of work:

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
MESAVERDE	6,358		<input type="checkbox"/>	<input type="checkbox"/>	SURFACE PRESSURE = 0#; KMGAS (TOP = 7228) ELIMINATED PER JENN MENDOZA
CAMEO	8,944		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	9,377		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

\_\_\_\_\_

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: JENN MENDOZA

Title: PERMIT TECH Date: 11/9/2010 Email: JENN.MENDOZA@WILLIAMS.COM

**Attachment Check List**

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
2590981	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2590982	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
2590980	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)