

IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.

CASING

| Casing Type | Size of Hole | Size of Casing | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Top | Cmt Bot | Status |
|-------------|--------------|----------------|-------|---------------|---------------|-----------|---------|---------|--------|
| CONDUCTOR | 24 | 18 | | 0 | 61 | 16 | 0 | 61 | VISU |
| SURF | 13+1/2 | 9+5/8 | | 0 | 2,448 | 570 | 0 | 2,448 | VISU |
| 1ST | 7+7/8 | 4+1/2 | | 0 | 8,024 | 940 | 3,020 | 8,024 | CBL |

ADDITIONAL CEMENT

Cement work date: _____

Details of work:

| Method used | String | Cementing tool setting/pref depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| | | | | | |

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analyses must be submitted to COGCC) |
|----------------|----------------|--------|--------------------------|--------------------------|---|
| | Top | Bottom | DST | Cored | |
| GREELEY SAND | 2,186 | | <input type="checkbox"/> | <input type="checkbox"/> | |
| MESAVERDE | 4,495 | | <input type="checkbox"/> | <input type="checkbox"/> | |
| CAMEO | 7,230 | | <input type="checkbox"/> | <input type="checkbox"/> | |
| ROLLINS | 7,988 | | <input type="checkbox"/> | <input type="checkbox"/> | |

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: ANGELA J NEIFERT

Title: PERMIT TECHNICIAN Date: 12/22/2010 Email: ANGELA.NEIFERT@WILLIAMS.COM

Attachment Check List

| Att Doc Num | Document Name | attached ? | |
|-----------------------------|-----------------------|---|--|
| <u>Attachment Checklist</u> | | | |
| | CMT Summary * | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Core Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| 2592456 | Directional Survey ** | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | DST Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Logs | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Other | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| <u>Other Attachments</u> | | | |
| 2592455 | FORM 5 SUBMITTED | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |

IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|--------------------------|---|----------------------------|
| Permit | REC RA BOND LOG DOC# 1800251 | 5/9/2011 2:05:06 PM |
| Permit | SURFACE CMT TKT DOC# 2072293, REQ CBL LOG | 4/19/2011 8:04:57 AM |

Total: 2 comment(s)