

FORM
5
Rev
02/08

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

1634061

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 96850 4. Contact Name: SANDRA SALAZAR
 2. Name of Operator: WILLIAMS PRODUCTION RMT COMPANY LLC Phone: (303) 629-8456
 3. Address: 1001 17TH STREET - SUITE #1200 Fax: (303) 629-8268
 City: DENVER State: CO Zip: 80202

5. API Number 05-045-17781-00 6. County: GARFIELD
 7. Well Name: SAVAGE Well Number: RWF 543-27
 8. Location: QtrQtr: NWSE Section: 27 Township: 6S Range: 94W Meridian: 6
 Footage at surface: Distance: 1639 feet Direction: FSL Distance: 1858 feet Direction: FEL
 As Drilled Latitude: 39.493478 As Drilled Longitude: -107.871433

GPS Data:
 Date of Measurement: 07/24/2009 PDOP Reading: 3.5 GPS Instrument Operator's Name: DON MEFFORD

** If directional footage at Top of Prod. Zone Dist.: 1451 feet. Direction: FSL Dist.: 536 feet. Direction: FEL
 Sec: 27 Twp: 6S Rng: 94W
 ** If directional footage at Bottom Hole Dist.: 1433 feet. Direction: FSL Dist.: 550 feet. Direction: FEL
 Sec: 27 Twp: 6S Rng: 94W

9. Field Name: RULISON 10. Field Number: 75400
 11. Federal, Indian or State Lease Number: CACOC56657

12. Spud Date: (when the 1st bit hit the dirt) 08/17/2009 13. Date TD: 08/24/2009 14. Date Casing Set or D&A: 08/25/2009

15. Well Classification:
 Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 7837 TVD** 7648 17 Plug Back Total Depth MD 7748 TVD** 7559

18. Elevations GR 5258 KB 5282 One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:
CBL AND RPM, mud

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	24	18		0	79	29	0	45	VISU
SURF	13+1/2	9+5/8		0	1,162	320	0	1,162	VISU
1ST	7+7/8	4+1/2		0	7,826	1,060	2,475	7,826	CBL

ADDITIONAL CEMENT

Cement work date: _____

Details of work:

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WASATCH G	1,360		<input type="checkbox"/>	<input type="checkbox"/>	
MESAVERDE	3,967		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	6,751		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	7,695		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: SANDRA SALAZAR

Title: PERMIT TECHNICIAN Date: 1/31/2011 Email: SANDRA.SALAZAR@WILLIAMS.COM

Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
1634061	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
1634062	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	RPM received 7/12/2011. NKP	7/13/2011 8:59:07 AM
Permit	See Images for scanned paper Form 5. It was given the same document # as the Cement Ticket. Paper resistivity log is missing. NKP	7/7/2011 11:50:07 AM

Total: 2 comment(s)