
Schlumberger
Array Induction Imager Tool
Dual Laterolog
Spectral Gamma Ray
Compensated Neutron
Litho-Density
Microlog
Sonic
Cable Head Tension
Mud Resistivity
Mud Temperature
Rm @ BHT
Rmf @ BHT
Rmc @ BHT
Source of Rmf and Rmc
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Rm @ BHT
Rmf @ BHT
Rmc @ BHT
Source of Rmf and Rmc
Rm @ Measured Temp
Rmf @ Measured Temp
Rmc @ Measured Temp
Source of Rmf and Rmc
Max Recorded Temperature
Circulation Stopped
Logger on Bottom
Unit Number
Witnessed By
Run Number
Depth Driller
Depth Logger
Bottom Logged Interval
Top Log Interval
Casing Driller
Casing Logger
Bit Size
Type Fluid in Hole
Density
Viscosity
pH
Fluid Loss
Source of Sample



Calibration Report

Database File: antelope 12-31_cbl.db
Dataset Pathname: pass3
Dataset Creation: Mon Jun 27 16:24:22 2011 by Log Std Casedhole 10121

Gamma Ray Calibration Report

Serial Number:	576	
Tool Model:	1.69TEKCO	
Performed:	Sun Jun 13 13:33:21 1993	
Calibrator Value:	1.0	GAPI
Background Reading:	0.0	cps
Calibrator Reading:	1.0	cps
Sensitivity:	1.0000	GAPI/cps

Cement Bond Log Calibration Report

Serial Number:	1		
Tool Model:	3-5tekco169		
Performed:	Mon Jun 27 16:10:47 2011		
Depth:	3064.54	ft	
Casing Diameter:	4.5	in	
	3' Spacing	5' Spacing	
Signal Zero:	3	0	mV
Calibrated Amplitude:	81.1961	81.1961	mV
Reading at Signal Zero:	0.03	0.03	V
Reading in Free Pipe:	2.23342	2.5	V
Gain:	35.4885	32.8729	
Offset:	1.93535	-0.986187	