

From: [Brian Macke](#)
To: [Baroumand, Soraya](#)
Cc: [Koehler, Bob](#); [Andrews, David](#); [Wayne Wise](#); [Mark Bonnie](#); [William Monroe](#); [Browning, Chuck](#)
Subject: RE: Corrective Action and Field Inspection Report API# 077-09123
Date: Friday, August 26, 2011 1:19:14 PM

Soraya,

Thank you for forwarding the your inspection report for the Vega Unit #9-421.

Delta is working to address the issues that you identified.

Regarding the weed issue on the well pad and access road, herbicide spraying was done on the areas that you identified last Wednesday, 8/24 and the treatment appears to be effective.

Regarding the issue with the Vega Unit #9-421 (produce, plug, or perform an MIT), Delta plans to perform an MIT on the well by the end of next week. Delta personnel will contact Chuck Browning prior to the MIT being performed so that he can have the opportunity to witness the test.

Please let me know if you need any additional information.

Brian Macke

Brian J. Macke, P.E.
Delta Petroleum Corporation
Phone: (303) 575-0386
Fax: (303) 575-0486
e-mail: bmacke@deltapetro.com

From: Baroumand, Soraya [<mailto:Soraya.Baroumand@state.co.us>]
Sent: Thursday, August 18, 2011 11:45 AM
To: Brian Macke
Cc: Koehler, Bob; Andrews, David
Subject: Corrective Action and Field Inspection Report API# 077-09123

If you have questions, contact me at the numbers provided below. Thank you.

Soraya Baroumand
Environmental Protection Specialist
Colorado Oil and Gas Conservation Commission
970-620-3277 cell, 970-876-9910 office

COGIS - Field Inspection Report	
API Number: 05-077-09123	Name: VEGA UNIT #9-421
Location: SENE 9 10S 93W	Lat: 39.20651 Long: -107.76757

Operator #:	Operator Name: DELTA PETROLEUM CORPORATION
Inspection Date: 8/5/2011	Inspector: SORAYA BAROUMAND

Inspection was: **Unsatisfactory**

Insp. Type: **SR** Insp. Stat: **SI** Reclamation (Pass, Interim or Fail): P&A (Pass/Fail):
 Brhd. Pressure: Inj. Pressure: T-C Ann. Pressure: UIC Violation Type:
 Violation: **Y** NOAV Sent: **N** Date Corrective Action Due: Date Remedied:

Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	PROVIDE MITIGATION AND MONITORING OF NOXIOUS WEEDS FOR LOCATION AND ACCESS ROAD PER RULE 1003.F AND PRODUCE, PLUG OR PERFORM A MECHANICAL INTEGRITY TEST PER RULE 326.B.
FENCECOMMENT	BARBED-WIRE FENCING W/PANEL GATE AT LOCATION
FIREWALL	SECONDARY CONTAINMENT FOR TANKS - GOOD
GENHOUSE	GOOD
MISC	WELL HAS BEEN SHUT-IN SINCE DECEMBER 2009. NO RECORD OF MIT ON FILE.
SPILCOM	NONE OBSERVED
SURFRH	STORMWATER BMPS CONSIST OF PERIMETER BERMS AND DIVERSION DITCHES ENCLOSING THE WELL PAD AND ARE SUSTAINING NATURAL VEGETATION. HOWEVER, BULL THISTLE, CANADIAN THISTLE, AND SOME MULLEIN (COLORADO-LISTED NOXIOUS WEEDS), WERE ALSO IDENTIFIED IN THE VICINITY OF THE PAD ENTRANCE AND IN SPOTS ALONG THE ACCESS ROAD.
TANKBAT	3 SINGLE-UNIT AND 1 QUAD-UNIT 3-PHASE HORIZONTAL SEPARATORS, 3-400 BBL TANKS, 1 COMBUSTOR
WELLSIGN	SIGNS AT LOCATION ENTRANCE, WELLHEADS AND TANK BATTERY

This email and any attachments are confidential and intended solely for the use of the individual or entity to whom this email is addressed. If you have received this email in error please notify the sender immediately by email and delete this email from your system. If you are not the intended recipient, you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this communication is strictly prohibited.

WARNING: Although the Company has taken reasonable precautions to ensure that no viruses are present in this email, the Company cannot accept responsibility for any loss or damage arising from the use of this email or attachments.

Delta Petroleum Corporation, 370 17th Street, Suite #4300, Denver, CO 80202
 www.deltapetro.com