
From: Eckman, Annie
Sent: Tuesday, October 25, 2011 2:28 PM
To: 'Todd Hutson'
Cc: Fischer, Alex
Subject: RE: Walker 12-1 Prod Pit NFA

Colorado Oil and Gas Conservation Commission (COGCC) staff has reviewed the Form 27 Site Investigation and Remediation Workplan submitted on August 19, 2011, for the referenced site. Based on review of data presented, it appears that no further action is necessary at this time at this site. However, should future conditions at the site be discovered of contaminant concentrations in soils exceeding COGCC standards or if groundwater is found to be significantly impacted, COGCC may require that further investigation and/or remediation be conducted. Please retain this email as confirmation.

Please call Alex Fischer at the number below should you have any questions.

Annie

Ann Clements Eckman, PG for
Alex Fischer
West Environmental Supervisor



1120 Lincoln Street, Suite 801
Denver, CO 80203
www.cogcc.state.co.us
303.894.2100 x 5138 (o)



Please consider the environment before printing this e-mail.

From: Todd Hutson [mailto:thutson@qrinc.com]
Sent: Friday, October 21, 2011 2:35 PM
To: Fischer, Alex
Cc: Eckman, Annie
Subject: RE: Pits

Alex,

Concerning the facility in the attached form 27, Quicksilver is confident that the analytical values for the samples collected by Foundation adequately represent the current conditions in the pit. Please advise your agreement so we may close the pit.

Thanks, Todd

R. Todd Hutson
thutson@qrinc.com
Environmental Manager
Quicksilver Resources Inc.
801 Cherry Street
Suite 3700, Unit 19
Fort Worth, Texas 76102
direct: 817-665-5434

mobile: 817-422-2883

From: Fischer, Alex [mailto:Alex.Fischer@state.co.us]
Sent: Thursday, October 20, 2011 11:43 AM
To: Todd Hutson
Cc: Eckman, Annie
Subject: RE: Pits

Todd,

For the Walker 12-5, Facility ID 286608.

Provide a Form 27 with diagram showing the four pits and locations:

**Facility number 286608 authorizes the four lined pits that you see on your image.
Locations are as follows:**

**152' X 152' – 40.576975, -107.782028
173' X 173' – 40.576522, -107.782952
206' X 206' – 40.576006, -107.783900
786' X 330' – 40.578056, -107.778133**

For the Walker 12-5 Flare Pit, facility ID 272982:

Provide a Form 27 with the following locations.

The last pit is located as follows:

40.576053, -107.778758

For the pit that was permitted and never constructed:

Provide a Form 27 explaining things. We will then do a visual inspection.

I believe that this should clean this part up.

Thanks

Alex

From: Todd Hutson [mailto:thutson@qrinc.com]
Sent: Thursday, October 20, 2011 10:16 AM
To: Fischer, Alex
Subject: Pits

Alex,

I was supposed to submit you a form 27 for one of those pits but I can't remember which one and for what purpose. Can you please jog my memory?

Thanks, Todd

R. Todd Hutson
thutson@qrinc.com
Environmental Manager
Quicksilver Resources Inc.
801 Cherry Street
Suite 3700, Unit 19
Fort Worth, Texas 76102
direct: 817-665-5434
mobile: 817-422-2883