Project Name: 297–2A release

Boring No.: 2

Project No: 1010–07

Logged By: G. Knell

Date: January 6, 2011. 14:00 – 15:30

Sheet: 1 of 1

boring at NE corner of pit

Graphic Log | Sample Location

5

0–9' (75% recovery) Sandy siltstone, trace of clay, brown to buff, iron stained (especially along bedding planes), thinly bedded (laminated), dry

10

9–14' (60% recovery) Same lithology as above (carbonaceous material in 6" zone at approx. 10'), dry

15

14–19' (50% recovery) Same lithology as above (some carbonaceous material. Noted at approx. 14.5'), dry

20

T.D. = 19

NOTES:
1. Iron staining characterized by limonite and hematite.
2. No hydrocarbon odors or PID readings throughout.

25

30

35

40

45

50

Drilling Method: hollow stem auger

Hole Diameter: 6"

Rig Type: CME – 75

Test Boring Elevation:

Sample Method: continuous barrel

KRW CONSULTING, INC.
8000 W. 14th Avenue
Suite 200
Lakewood, CO 80214
(303) 239–9011