

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/05/2011

Document Number:

664000092

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	API Number	Facility ID	Loc ID	Tracking Type
	061-06376	213015	324833	
Facility Name: FRAZEE B 4		Inspector Name: LEONARD, MIKE		

Operator Information:OGCC Operator Number: 8005 Name of Operator: BERRY ENERGY INC*WALTERAddress: 1717 WASHINGTON AVECity: GOLDEN State: CO Zip: 80401-**Contact Information:**

Contact Name	Phone	Email	Comment
Whiting, Jim	(719) 688-0064	jimwhiting_99@yahoo.com	pumper
Bidle, Holly	(303) 279-0190	berryenergyhreed@comcast.net	Regulatory manager

Compliance Summary:QtrQtr: NENW Sec: 9 Twp: 19S Range: 50W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/30/2008	200197834	CA	PR	S			N
11/08/2000	200011929	PR	PR	S	I	P	N
06/21/2011	200313053	SR	PA	U			Y
02/02/1996	500145107	PR	PR			P	N
11/16/1994	500145106		PR				
04/14/2008	200130315	PR	PR	U			Y
04/30/2008	200189292	PR	PR	S			N
08/22/1997	500145108	PR	PR			F	Y
10/30/2008	200197836	SR	PA	U	F	F	N
10/22/1996	500145110	PR	PR			F	Y
05/12/2010	200248646	SR	PA	U	F	F	Y
01/12/1999	500145111	PR	PR			P	N
12/28/2010	200290394	SR	PA	U	F	F	Y
01/04/2008	200125060	PR	PR	U			Y

Inspector Comment:

SEE COMMENTS IN FINAL RECLAMATION TAB

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num
213015	WELL	PA	10/30/2008	OW	061-06376

Equipment:Location Inventory

Inspector Name: LEONARD, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

Predrill

Location ID: 324833

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 213015

API Number: 061-06376

Status: PA

Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS File: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Final Reclamation/ Abandoned Location:

Inspector Name: LEONARD, MIKE

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: LEASE IN GRASSLAND

Well plugged Pass

Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% Fail

Cropland: perennial forage _____

Weeds present Fail

Subsidence Pass

Comment: PUMPJAC BASE, CEMENT PAD AND RISERS REMAIN. WEEDS HAVE OVERGROWN DISTURBED AREAS.

Corrective Action: REMOVE REMAINING EQUIPMENT AND CONTROL WEEDS

Date **12/30/2011**

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

COGCC Comments

Comment	User	Date
SEE COMMENTS IN FINAL RECLAMATION TAB	leonardm	11/04/2011