

FORM  
INSPRev  
05/11

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/04/2011

Document Number:

663900043

Overall Inspection:

Satisfactory

## FIELD INSPECTION FORM

Location Identifier	API Number	Facility ID	Loc ID	Tracking Type
	017-06431	207496	380451	
Facility Name: SCHALLENBERGER 1-32			Inspector Name: QUINT, CRAIG	

## Operator Information:

OGCC Operator Number: 10330 Name of Operator: INVESTMENT EQUIPMENT LLC

Address: 17509 COUNTY ROAD 14

City: FT MORGAN State: CO Zip: 80701

## Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave	970-867-9007	investmentequipment@cox.net	

## Compliance Summary:

QtrQtr: SWSW Sec: 32 Twp: 12S Range: 50W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/06/2010	200243225	SR	PA	S	P	P	N

## Inspector Comment:

RIG CREW IS IN PROCESS OF LAYING DOWN DRILL COLLARS TO PREPARE FOR PLUGGING OPERATION.

## Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num
207496	WELL	PA	02/28/1985	OW	017-06431

## Equipment:

## Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: 1	Production Pits: _____
Condensate Tanks: _____	Water Tanks: 1	Separators: 1	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: 1
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: 1	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

## Location

## Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
ADEQ	Satisfactory	2 track through pasture		

## Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DRILLING/RECOMP	Satisfactory			

Inspector Name: QUINT, CRAIG

Emergency Contact Number: (S/U/V) Satisfactory	Corrective Date: _____
Comment: _____	
Corrective Action: _____	

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 380451

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Group	User	Comment	Date
OGLA	koepsear	Per Ted Pagano, Investment Equipment is re-entering the hole and do not expect to use mud during the re-entry. They do intend to use fresh water which once brought back to the surface will be disposed at an injection facility. If old mud and cuttings are brought up during the re-entry the will be incorporated into the pad and lease road. Materials will not be spread on the rangeland.	07/19/2011
OGLA	koepsear	If old mud and cuttings are to be incorporated in the location the operator must submit a Waste Management Plan meeting the general requirements of Rule 907.a.. Submit the Waste Management Plan on a Form 4 Sundry Notice via email to ogccenvirosundry@state.co.us.	08/03/2011
Permit	princen	Ted Pagano is not a registered agent for Investment Equipment LLC.	06/28/2011
OGLA	koepsear	Ready to pass 8/03/2011.	07/19/2011
Permit	princen	Signed Form 1A was processed on July 12, 2011. NKP	07/13/2011
Data Entry	greenstm	CHECK SURFACE OWNER: OPERATOR OMITTED SURFACE OWNER TYPE - DATA ENTERED FOR SUMISSION - FEE. CHECK 9. CULTURAL DISTANCE IN FEET TO RAILROAD.	06/28/2011

**Wildlife BMPs:**

BMP Type	Comment
PROPOSED BMPs	<p>BMP Plan</p> <p>Investment Equipment, LLC</p> <p>17509 COUNTY ROAD 14</p> <p>FT MORGAN , CO 80701</p> <p>c/o Ted Pagano</p> <p>970 - 590 -3944</p> <p>Stormwater Discharges Associated with Construction Oil and Gas Activity. Application has been filed with Colorado Department of Public Health and Environment Water Quality Control Division and is pending. Approved permit will be in place before any dirt work begins, if any.</p> <p>Re- Entry, Schallenberger No. 1 -32 well</p> <p>T12S, R50W</p> <p>Sec. 32: SW1/4SW1 /4</p> <p>Cheyenne County, Colorado</p> <p>Description of Well Site and Construction Area</p> <p>1 -3 acre site with access road for drilling of oil and gas well. Terrain is flat dry Rangeland ground containing native grass species. No receiving waters will be affected by well pad. There will be no drilling pits associated with the drillsite. Disturbed areas will be reseeded within 6 months weather permitting. Silt fences will be installed on low side site of drill site. Topsoil</p> <p>will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in.</p> <p>Stormwater Management Plan (SWMP) is on file in Investment Equipment, LLC Office.</p> <p>Spill Prevention, Control and Countermeasure Plan is on file in Investment Equipment, LLC Office.</p>

**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Well**

Facility ID: 207496 API Number: 017-06431 Status: PA Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Codell Well Service Pusher/Rig Manager: Ray Brown

Permit Posted: Satisfactory Access Sign: Satisfactory

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: NO Unlined Pit: YES Closed Loop: YES Semi-Closed Loop: NO

Multi-Well: NO Disposal Location: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS File: \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Access Roads	Regraded _____	Contoured _____	Culverts removed _____
	Gravel removed _____		
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____		
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____	Subsidence _____		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date	

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

**Pits:**

Pit Type: Workover Lined: NO

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Pit (S/U/V): \_\_\_\_\_ Comment:

Corrective Action:  Date: \_\_\_\_\_