

FORM
INSPRev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/04/2011

Document Number:

663900046

Overall Inspection:

Satisfactory

FIELD INSPECTION FORM

Location Identifier	API Number	Facility ID	Loc ID	Tracking Type
	073-06387	413101	413090	
Facility Name: ALOHA MULA 3			Inspector Name: QUINT, CRAIG	

Operator Information:

OGCC Operator Number: 96340 Name of Operator: WIEPKING-FULLERTON ENERGY LLC

Address: 4600 S DOWNING ST

City: ENGLEWOOD

State: CO

Zip: 80113

Contact Information:

Contact Name	Phone	Email	Comment
Halde, Kerry	719-346-0653 off	haldesand@centurytel.net	719-340-0329 cell

Compliance Summary:

QtrQtr: NESW Sec: 19 Twp: 10S Range: 55W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/06/2009	200222844	DG	DG	S			N

Inspector Comment:

CENTRAL BATTERY 1300' SOUTH @ ALOHA MULA #1.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num
413101	WELL	PR	08/17/2011	DA	073-06387

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: 1	Wells: 1	Production Pits: _____
Condensate Tanks: _____	Water Tanks: 3	Separators: 3	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: 1
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: 8	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
ADEQ	Satisfactory	2 TRACK THROUGH PASTURE		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	NEW WELL (SIGNS ON ORDER)	INSTALL SIGNS A.S.A.P.	02/04/2012

Inspector Name: QUINT, CRAIG

Emergency Contact Number: (S/U/V) _____	Corrective Date: _____
Comment: _____	
Corrective Action: _____	

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION FENCED WITH WIRE		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pump Jack	1	Satisfactory	LUFKIN 456D		
Ancillary equipment	3	Unsatisfactory	PROPANE TANK, GAS SCRUBBER, CHEMICAL TANK W/O CONTAINMENT	INSTALL CONTAINMENT FOR CHEMICAL TANK	02/04/2012
Prime Mover	1	Satisfactory	GAS ENGINE, M&M		

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill			
Location ID: 413090			
Site Preparation:			
Lease Road Adeq.: _____		Pads: _____	Soil Stockpile: _____
Corrective Action: _____		Date: _____	CDP Num.: _____
Form 2A COAs:			
Group	User	Comment	Date
Agency	ashm	Site visit conducted on July 17, 2009.	07/28/2009
Agency	walkerv	SEE ATTACHED NOTICE CONCERNING OPERATING REQUIREMENTS FOR WILDLIFE PROTECTION	07/29/2009
Wildlife BMPs:			

BMP Type	Comment
PROPOSED BMPs	<p>Certification to Discharge</p> <p>Under</p> <p>CDPS General Permit COR -03000</p> <p>Stormwater Discharges Associated with Construction</p> <p>T10S, R55W</p> <p>Sec. 19: NE1 /4SW1 /4</p> <p>Lincoln County, Colorado</p> <p>U -iop BMP Plan</p> <p>Wiepking - Fullerton Energy, L.L.C.</p> <p>4600 S. Downing St.</p> <p>Englewood, CO 80113</p> <p>303 - 789 -1798</p> <p>303 - 761 -9067 (fax)</p> <p>Certification Number COR 39788</p> <p>Description of Well Site and Construction Area</p> <p>1 -3 acre site with access road for drilling of oil and gas well. Terrain is flat with native grass and sagebrush. No receiving waters will be affected by well pad. Drilling pits closed and reclaimed with the drillsite reseeded within 6 months weather permitting. Silt fences will be installed on low side site of drill site. Topsoil will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in or manure spread.</p> <p>Stormwater Management Plan (SWMP) is on file in Wiepking - Fullerton Energy, L.L.C. office.</p> <p>Spill Prevention, Control and Countermeasure Plan is on file in Wiepking-Fullerton Energy, L.L.C. office.</p>

Stormwater:**Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Inspector Name: QUINT, CRAIG

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 413101 API Number: 073-06387 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS File: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

Inspector Name: QUINT, CRAIG

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Fail

1003 f. Weeds Noxious weeds? P

Comment: NEW WELL, PITS HAVE BEEN BACK FILLED AND LOCATION RIPPED AND CONTOURED. HAS NOT BEEN SEEDED YET. CONTINUE WITH INTERIM RECLAMATION.

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Inspector Name: QUINT, CRAIG

Corrective Action:					Date	
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	MHSP	Fail	INSTALL CONTAINMENT FOR CHEMICAL TANK
S/U/V: Satisfactory Corrective Date: _____						
Comment: _____						
CA: _____						