



Carmel 21-33 PW tank with NFPA label installed
after prior inspection

11.29.2011 09:44



Carmel 21-33 unused equipment, 2nd failed inspection notice for same issue at his location

11.29.2011 09:45