


COGIS - Field Inspection Report

	
API Number: 05-043-06197	Name: CROAKER #11-10
Location: NWNW 10 20S 69W	Lat: 38.329786 Long: -105.102423
Operator #:	Operator Name: PINE RIDGE OIL & GAS LLC
Inspection Date: 5/9/2011	Inspector: MIKE LEONARD
Inspection was: Unsatisfactory	

Insp. Type: CA	Insp. Stat: DA	Reclamation (Pass, Interim or Fail):	P&A (Pass/Fail):
Brhd. Pressure:	Inj. Pressure:	T-C Ann. Pressure:	UIC Violation Type:
Violation: N	NOAV Sent: N	Date Corrective Action Due:	Date Remedied:

Pit Inspection

Pit Type: **SP** Oil on Pit: Freeboard:

Number of Pits: **1** Number covered or lined: **1** Number uncovered or unlined:

Comments: **LINED DRILLING PIT OPEN AND FENCED NO OIL PRESENT ADEQUATE FREEBOARD**

Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	FINISH PLUGGING OUT WELL
FENCECOMMENT	LOCATION FENCED WITH BARBED WIRE
GENHOUSE	GOOD
WORKOV	WITNESS JAVERNICK CREW LOWER PLUG TO 680' +/- MIX AND DUMP 10 80# SACKS OF SACKRETE ONTO PLUG.