

# COGIS - Field Inspection Report

API Number: <b>05-043-06197</b>		Name: <b>CROAKER #11-10</b>	
Location: <b>NWNW 10 20S 69W</b>		Lat: <b>38.329786</b> Long: <b>-105.102423</b>	
Operator #:		Operator Name: <b>PINE RIDGE OIL &amp; GAS LLC</b>	
Inspection Date: <b>5/10/2011</b>		Inspector: <b>MIKE LEONARD</b>	
Inspection was: <b>Satisfactory</b>			

Insp. Type: <b>CA</b>	Insp. Stat: <b>DA</b>	Reclamation (Pass, Interim or Fail): <b>P&amp;A (Pass/Fail):</b>	
Brhd. Pressure:	Inj. Pressure:	T-C Ann. Pressure:	UIC Violation Type:
Violation: <b>N</b>	NOAV Sent: <b>N</b>	Date Corrective Action Due:	Date Remedied:

## Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	CUT AND CAP CASING RECLAIM LOCATION
WORKOV	JAVERNICK CREW HAD MIXED AND DUMPED 10 MORE 80# SACKS OF SACKRETE ON 5/10/2011. WITNESS REDI-MIX DUMP 11 YARDS GROUT MIX TO FILL CASING TO SURFACE.