

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/06/2011

Document Number:

663800050

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	288314	334768		LONGWORTH, MIKE

**Operator Information:**OGCC Operator Number: 96850 Name of Operator: WILLIAMS PRODUCTION RMT COMPANY LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Moss, Brad	(970) 285-9377	Brad.Moss@Williams.com	Production foreman

**Compliance Summary:**QtrQtr: NWNE Sec: 2 Twp: 7S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/01/2010	200285197	PR	PR	S			N
06/12/2009	200213618	PR	PR	S			N

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
288189	WELL	PR	12/05/2006	LO	045-13171	HOAGLUND PA 331-2	X
288313	WELL	PR	08/20/2007	LO	045-13215	HOAGLUND PA 341-2	X
288314	WELL	PR	08/20/2007	LO	045-13214	HOAGLUND PA 41-2	X
288315	WELL	PR	12/11/2006	LO	045-13213	HOAGLUND PA 31-2	X
288316	WELL	PR	12/11/2006	LO	045-13212	HOAGLUND PA 431-2	X
288317	WELL	PR	08/20/2007	LO	045-13211	HOAGLUND PA 441-2	X
288318	WELL	PR	12/11/2006	LO	045-13210	HOAGLUND PA 531-2	X
288319	WELL	PR	08/20/2007	LO	045-13209	HOAGLUND PA 541-2	X
288320	WELL	PR	12/11/2006	LO	045-13208	HOAGLUND PA 342-2	X
288321	WELL	PR	08/20/2007	LO	045-13207	HOAGLUND PA 42-2	X
288322	WELL	PR	12/11/2006	LO	045-13206	HOAGLUND PA 332-2	X
288323	WELL	PR	12/11/2006	LO	045-13205	HOAGLUND PA 32-2	X
288324	WELL	PR	08/21/2007	LO	045-13204	HOAGLUND PA 542-2	X
288325	WELL	PR	08/20/2007	LO	045-13203	HOAGLUND PA 532-2	X
288326	WELL	PR	08/20/2007	LO	045-13202	HOAGLUND PA 432-2	X
288327	WELL	PR	08/20/2007	LO	045-13201	HOAGLUND PA 442-2	X

**Equipment:**Location Inventory

Inspector Name: LONGWORTH, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

<b>Location</b>
-----------------

<b>Lease Road:</b>				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) _____	Satisfactory _____	Corrective Date: _____
Comment: _____		
Corrective Action: _____		

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Satisfactory	continue weed control		
TRASH	Satisfactory			

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory			
SEPARATOR	Satisfactory			
WELLHEAD	Satisfactory			

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	6	Satisfactory			
Plunger Lift	6	Satisfactory			
Plunger Lift	10	Satisfactory			
Horizontal Heated Separator	10	Satisfactory			

Bird Protectors	8	Satisfactory			
-----------------	---	--------------	--	--	--

**Tanks/Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,
S/U/V:		Comment:		

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
-----------	--

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

**Tanks/Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	,
S/U/V:	Satisfactory	Comment:		

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Inspector Name: LONGWORTH, MIKE

**Tanks/Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	39.471860,107.961630
S/U/V:	Comment:			

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
-----------	--

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

<b>Venting:</b>		
Yes/No	Comment	
YES	bradens venting	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 334768

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 288189      API Number: 045-13171      Status: PR      Insp. Status: PR

Facility ID: 288313      API Number: 045-13215      Status: PR      Insp. Status: PR

Facility ID: 288314      API Number: 045-13214      Status: PR      Insp. Status: PR

Facility ID: 288315      API Number: 045-13213      Status: PR      Insp. Status: PR

Facility ID: 288316      API Number: 045-13212      Status: PR      Insp. Status: PR

Facility ID: 288317      API Number: 045-13211      Status: PR      Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Facility ID: 288318 API Number: 045-13210 Status: PR Insp. Status: PR

Facility ID: 288319 API Number: 045-13209 Status: PR Insp. Status: PR

**BradenHead**

Comment: gauge on braden @81 psi

CA:

CA Date:

Facility ID: 288320 API Number: 045-13208 Status: PR Insp. Status: PR

Facility ID: 288321 API Number: 045-13207 Status: PR Insp. Status: PR

Facility ID: 288322 API Number: 045-13206 Status: PR Insp. Status: PR

Facility ID: 288323 API Number: 045-13205 Status: PR Insp. Status: PR

Facility ID: 288324 API Number: 045-13204 Status: PR Insp. Status: PR

Facility ID: 288325 API Number: 045-13203 Status: PR Insp. Status: PR

Facility ID: 288326 API Number: 045-13202 Status: PR Insp. Status: PR

Facility ID: 288327 API Number: 045-13201 Status: PR Insp. Status: PR

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Corrective Action:					Date	
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
S/U/V: _____ Corrective Date: _____						
Comment: _____						
CA: _____						