

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/08/2011

Document Number:
659400100

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>258753</u>	<u>333925</u>		<u>DURAN, JOHN</u>

Operator Information:

OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC

Address: 382 CR 3100

City: AZTEC State: NM Zip: 87410

Contact Information:

Contact Name	Phone	Email	Comment
Montoya, Sam	719-845-2107/719-859-1117	sam_montoya@ xtoenergy.com	
Blatnick, Bill	719-845-2112/719-859-3370	bill_blatnick@ xtoenergy.com	
Jaramillo, Diane	505-333-3109	diane_jaramillo@xtoenergy.com	Eng. Mngr - Reg., Aztec,NM
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@ xtoenergy.com	

Compliance Summary:

QtrQtr: SESW Sec: 4 Twp: 35S Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/29/2003	200038200	PR	PR	S		P	N
02/13/2008	200127337	PR	PR	S			N
03/06/2005	200068027	PR	PR	S		P	N

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
258753	WELL	PR	02/24/2001	GW	071-07142	HILL RANCH 04-14V <input checked="" type="checkbox"/>
258966	WELL	PR	10/23/2001	GW	071-07175	HILL RANCH 04-14R <input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Vertical Separator	1	Satisfactory			
Gas Meter Run	1	Satisfactory			
Progressive Cavity	1	Satisfactory			
Deadman # & Marked	3	Satisfactory			

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 333925

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 258753 API Number: 071-07142 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Inspector Name: DURAN, JOHN

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Inspector Name: DURAN, JOHN

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____
 Comment: _____
 CA: _____

Pits:

Pit Type: Evaporation Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____

Fencing:
 Fencing Type: _____ Fencing Condition: _____
 Comment: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____
 Pit (S/U/V): Satisfactory Comment: 30' X 80', shared.
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Crew on site picking up tubing. Orange trailer on site.	duranj	12/13/2011