

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/17/2011

Document Number:  
662300019

Overall Inspection:  
Satisfactory

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>222181</u>	<u>312756</u>		

**Operator Information:**

OGCC Operator Number: 10195 Name of Operator: WINTER RIDGE ENERGY LLC  
Address: 555 17TH STREET - SUITE 950  
City: DENVER State: CO Zip: 80202

**Contact Information:**

**Compliance Summary:**

QtrQtr: SWNW Sec: 23 Twp: 4N Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/24/2011	200315513	PR	PR	S			N
03/16/2010	200240398	PR	PR	S			N
04/18/2000	200007124	ID	SI	S		P	N

**Inspector Comment:**

appears to be vacuum suck at wellhead where conduit goes in to well.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
222181	WELL	PR	06/26/2006		081-05119	ILES DOME UNIT 8

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	No sign.	Install sign per rule	<b>01/01/2012</b>

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: \_\_\_\_\_

Comment: see sign rule

Corrective Action: see sign rule

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	shingles from eletric pannel shack on ground. old wire/trash on ground. old tubing.	remove all trash and unessary equipment.	01/01/2012

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	fence down and lying on ground	remove or repair fence	12/12/2012

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pump Jack	1	Satisfactory	well on down hole pump. pumpjack in pieces at wellhead.	remove pumpjack	06/01/2012

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 312756

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Wildlife BMPs:**

**Stormwater:**

**Comment:**

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS: \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

\_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

- 1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Inspector Name: NEIDEL, KRIS

Access Roads      Regraded \_\_\_\_\_      Contoured \_\_\_\_\_      Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_      Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_      Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_      Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_      Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_      Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_      Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_