

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/22/2011

Document Number:

661700074

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>215346</u>	<u>325762</u>		<u>LABOWSKIE, STEVE</u>

Operator Information:OGCC Operator Number: 10000 Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 501 WESTLAKE PARK BLVDCity: HOUSTON State: TX Zip: 77079**Contact Information:**

Contact Name	Phone	Email	Comment
Fauth, Dan	(970) 247-6800/ (505) 330-1954	daniel.fauth@bp.com	Environmental Coordinator (Durango)
Best, Julie	(970) 375-7540/ (970) 394-0131	julie.best@bp.com	Environmental Advisor
Kerr, Kyle	(970) 382-3690/ (970) 317-0623	kyle.kerr@bp.com	Environmental Advisor

Compliance Summary:QtrQtr: SENW Sec: 12 Twp: 34N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/02/1995	500148869	PR	PR				N
01/08/2002	200025547	PR	PR	S		P	N
11/08/2006	200103049	PR	PR	S		P	N
06/24/2003	200041309	PR	PR	S		P	N
10/10/1997	500148871	PR	PR			P	N
01/05/2001	200015027	PR	PR	S		P	N
10/06/1999	500148872	PR	PR			P	N
07/19/2005	200077105	PR	PR	S		P	N
09/20/1996	500148870	PR	PR			P	N
11/16/1994	500148868	PR	PR			P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
215346	WELL	PR	01/23/1989	GW	067-06951	ALICE LORENZ GAS UNIT 1	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: LABOWSKIE, STEVE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

<u>Location</u>

<u>Signs/Marker:</u>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<u>Fencing:</u>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION		barbed wire, no gate		
WELLHEAD				

<u>Equipment:</u>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1				
Pump Jack	1		sound walls on one side		
Horizontal Heated Separator	1				
Ancillary equipment	1		telemetry		
Deadman # & Marked	4		one anchor outside fence		

<u>Venting:</u>		
Yes/No	Comment	

<u>Flaring:</u>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

--	--	--	--	--

Predrill

Location ID: 325762

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 215346 API Number: 067-06951 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Inspector Name: LABOWSKIE, STEVE

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Inspector Name: LABOWSKIE, STEVE

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____		Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____		Subsidence _____	
Comment: _____			
Corrective Action: _____			Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____