

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/20/2011

Document Number:

662300067

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>212215</u>	<u>324634</u>		<u>NEIDEL, KRIS</u>

Operator Information:OGCC Operator Number: 100200 Name of Operator: LONE PINE GAS INCAddress: 6704 E LONG AVECity: ENGLEWOODState: COZip: 80112**Contact Information:**

Contact Name	Phone	Email	Comment
shute, stephen	970-928-9208	pipeline@rof.net	

Compliance Summary:QtrQtr: SWSE Sec: 28 Twp: 9N Range: 81W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/13/2003	200042775	PR	PR	S		P	N
08/14/2002	200030640	PR	PR	S		P	N
08/12/2004	200058709	PR	PR	S		P	N
08/03/1999	500143867	PR	PR			P	N
08/18/2010	200279902	PR	PR	S			N
08/02/2001	200018428	PR	PR	S		P	N
08/21/1998	500143866	PR	PR			P	N
07/25/1997	500143865	PR	PR			P	N
07/13/2000	200007938	PR	PR	S		P	N
03/27/2007	200108001	ID	SI	S	I	P	N
03/28/2006	200087677	ES	PR	U	I	F	Y

Inspector Comment:

main collection facility on this well.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
212215	WELL	PR	07/19/1974	OW	057-06108	MARGARET SPAULDING 14	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: NEIDEL, KRIS

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Violation	Labels on tanks are not in compliance	Label all tanks per rule 210.d.	02/01/2012

Emergency Contact Number: (S/U/V) _____ Violation _____ Corrective Date: 02/01/2012

Comment: Emergency contact number not on sign.

Corrective Action: Install sign with emergency contact number. rule 210.b.

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
Crude Oil	Flow Line	<= 5 bbls	volume unknown, free product in stream. downstream from discharge.	02/01/2012
Crude Oil	Separator	<= 5 bbls	inside main separator pumphouse, prevent spills and remove contaminated soil	02/01/2012

☒ Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Separator	2	Unsatisfactory	separator appear to not be working, oil in pits.	improve separator efficiency.	02/01/2012
Pump Jack	1	Satisfactory			

Inspector Name: NEIDEL, KRIS

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	6	300 BBLS	STEEL AST	,

S/U/V:	Violation	Comment:	
Corrective Action:	label tanks	Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	7	300 BBLS	STEEL AST	,

S/U/V:	Violation	Comment:	
Corrective Action:	label tanks.	Corrective Date:	02/01/2012

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:	
Yes/No	Comment
YES	is form 4 on file for venting of gas in pit?

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324634

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 212215 API Number: 057-06108 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Inspector Name: NEIDEL, KRIS

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Inspector Name: NEIDEL, KRIS

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____		Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____		Subsidence _____	
Comment: _____			
Corrective Action: _____			Date _____
Overall Final Reclamation			

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits:

Pit Type: Produced Water	Lined: NO	Pit ID: _____	Lat: _____	Long: _____
--------------------------	-----------	---------------	------------	-------------

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: _____

Pit (S/U/V): Violation Comment: this is last pit prior to surface discharge. there is free product on top of water in pit, there is free product in discharge area, there is free product in stream

Corrective Action: stop production until free product can be cleaned and prevented. Date: 02/02/2012

Pits:

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: _____

Pit (S/U/V): _____ Comment: this is 2nd to last pit prior to surface discharge. there is free product around edge of water in pit, free product on shore of pit.

Corrective Action: stop production until free product can be cleaned and prevented.

Date: 02/01/2012

Pits:

Pit Type: Produced Water Lined: YES Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: PVC Liner Condition: Inadequate

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: Holes

Comment: no netting on pit that is venting gas, lots of oil

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: _____

Pit (S/U/V): Violation Comment: _____

Corrective Action: close pit. consult with COGCC staff on pit closure.

Date: 07/01/2012

Pits:

Pit Type: Produced Water Lined: YES Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: PVC Liner Condition: Inadequate

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: _____

Netting:

Netting Type: Metal Grid Netting Condition: Gaps

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: YES 2+ feet Freeboard: _____

Pit (S/U/V): Violation Comment: _____

Corrective Action: improve separator efficiency to prevent overload of pit.

Date: 02/01/2012