

PIONEER

NATURAL RESOURCES USA, INC.

Silva 22-6V

API 05-071-08143

T33S R67W Sec. 6: SENW

CR. 31.9

Lat. 37.20235/Long. 104.93157

EMERGENCY No.: 911 or 719-846-7898 (24 hours)

WDID 1911783 / PERMIT #72968-F

12.12.2011 09:02



spill path

12.12.2011 09:05



Drainage channel off Silva 22-6V location
No mechanism of filtering sediment at end
of riprap

12.12.2011 09:21

A photograph of a snowy forest floor. In the foreground, there is a thick layer of white snow. A path of brown sediment, likely pine needles or organic matter, has migrated from a wooded area in the background towards the foreground. The path is visible as a dark, winding line through the snow. The background is filled with tall, dark green pine trees. The sky is overcast and grey.

sediment migration in spill
path off location

12.12.2011 09:05