

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

01/23/2012

Document Number:

663900444

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|---------------|---------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: |
| | <u>252840</u> | <u>303297</u> | | <u>QUINT, CRAIG</u> |

Operator Information:OGCC Operator Number: 94701 Name of Operator: FIDELITY EXPLORATION & PRODUCTION COMPANYAddress: 1700 LINCOLN ST STE 2800City: DENVERState: COZip: 80203**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------------------|-----------------------|---------------------|
| Andrews, Gary | 970-354-7477 (Idalia) | gary.andrews@wbip.com | 970-332-0678 (Wray) |

Compliance Summary:QtrQtr: SWSE Sec: 32 Twp: 4S Range: 43W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 12/08/2010 | 200286912 | PR | PR | S | | | N |
| 08/11/2006 | 200097084 | PR | PR | S | | P | N |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 252840 | WELL | PR | 03/27/1982 | GW | 125-06716 | DEVLIN 34-32 | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|--|-------------------|------|
| Access | Satisfactory | GRAVEL ROAD THROUGH PASTURE WITH AREAS OF EROSION. | | |

Inspector Name: QUINT, CRAIG

| Signs/Marker: | | | | |
|----------------------|-----------------------------|-----------------------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | LEASE SIGN MOUNTED TO FENCE | | |
| TANK LABELS/PLACARDS | Satisfactory | METAL SIGN BY TANK | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|-----------------------------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | STEEL PANELS AROUND ALL EQUIPMENT | | |

| Equipment: | | | | | |
|---------------------|---|-----------------------------|--------------------------------------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Gas Meter Run | 1 | Satisfactory | | | |
| Pump Jack | 1 | Satisfactory | 25 JENSEN | | |
| Vertical Separator | 1 | Satisfactory | | | |
| Prime Mover | 1 | Satisfactory | ELEC MOTOR | | |
| Ancillary equipment | 1 | Satisfactory | ELEC PANEL, METHANOL TANK (NOT USED) | | |

Tanks/Berms: ☐ New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|----------|----------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLS | Open Top | 39.661680,-102.202710 |

S/U/V: Satisfactory Comment: 210BBL OTFGWT 50% BURIED WITH ADEQUATE WIRE WILDLIFE SCREENING.

Corrective Action: _____ Corrective Date: _____

Paint

| Condition | Adequate |
|-----------|----------|
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

| Berms | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| | | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 303297

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 252840 API Number: 125-06716 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ Lat _____ Long _____
 GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Fail

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Fail Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE PASTURE.

Inspector Name: QUINT, CRAIG

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Fail | Gravel | Fail | | | |

S/U/V: Unsatisfactory Corrective Date: 04/23/2012

Comment: AREAS OF EROSION ON LEASE ROAD AND WELL PAD.

CA: DESIGN AND IMPLEMENT EROSION CONTROL MEASURES (BMP'S)