

Inspector Name: HICKEY, MIKE

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

01/26/2012

Document Number:

658500095

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|---------------|---------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: |
| | <u>273715</u> | <u>332731</u> | | <u>HICKEY, MIKE</u> |

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

| | | | |
|--------------|-------|------------------------|---------|
| Contact Name | Phone | Email | Comment |
| Berlin, John | | john.berlin@encana.com | |

Compliance Summary:QtrQtr: NWNW Sec: 10 Twp: 3N Range: 65W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 05/03/2005 | 200075289 | CO | PR | S | | P | N |
| 11/04/2004 | 200062626 | DG | ND | S | | P | N |

Inspector Comment:

Routine inspection of API #05-123-22396 Aristocrat Federal #1-2-10

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|------------------------------------|-------------------------------------|
| 249111 | WELL | PR | 03/02/2004 | OW | 123-16913 | FEDERAL 11-10 | <input checked="" type="checkbox"/> |
| 273615 | WELL | PR | 03/10/2010 | GW | 123-22386 | ARISTOCRAT ANGUS FEDERAL 2-10 | <input checked="" type="checkbox"/> |
| 273715 | WELL | PR | 05/01/2005 | GW | 123-22396 | ARISTOCRAT ANGUS FEDERAL 1-2-10 | <input checked="" type="checkbox"/> |
| 280927 | WELL | AL | 05/27/2009 | LO | 123-23331 | ARISTOCRAT ANGUS FEDERAL 1-1-10 | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|---------|-----------------------------|---------|-------------------|---------|
| BATTERY | Satisfactory | | | |

Inspector Name: HICKEY, MIKE

| | | | | |
|----------|--------------|--|--|--|
| WELLHEAD | Satisfactory | | | |
|----------|--------------|--|--|--|

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|--------------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |
| TANK BATTERY | Satisfactory | | | |

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Emission Control Device | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |
| Bird Protectors | 2 | Satisfactory | | | |
| Horizontal Heated Separator | 1 | Satisfactory | | | |

Tanks/Berms: ☐ New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|---|----------|----------------|------------------|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | , |
| S/U/V: | | Comment: | | |
| Corrective Action: | | | | Corrective Date: |

Paint

| Condition | Adequate |
|------------------|----------|
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Inspector Name: HICKEY, MIKE

Tanks/Berms:

☐ New Tank

Tank ID: _____

| | | | | |
|-----------|---|----------|-----------|----------------------|
| Contents | # | Capacity | Type | SE GPS |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | 40.246690,104.654820 |

| | | | |
|--------------------|--------------|------------------|--|
| S/U/V: | Satisfactory | Comment: | |
| Corrective Action: | | Corrective Date: | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

Venting:

| | | |
|--------|---------|--|
| Yes/No | Comment | |
| | | |

Flaring:

| | | | | |
|------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 332731

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 249111 API Number: 123-16913 Status: PR Insp. Status: PR

Facility ID: 273615 API Number: 123-22386 Status: PR Insp. Status: PR

Facility ID: 273715 API Number: 123-22396 Status: PR Insp. Status: PR

Facility ID: 280927 API Number: 123-23331 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

Inspector Name: HICKEY, MIKE

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Inspector Name: HICKEY, MIKE

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____

Corrective Date: _____

Comment: _____

CA: _____