

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
01/26/2012

Document Number:
659700059

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>Baroumand, Soraya</u>
	<u>297253</u>	<u>335526</u>		

Operator Information:

OGCC Operator Number: <u>10071</u>	Name of Operator: <u>BARRETT CORPORATION* BILL</u>
Address: <u>1099 18TH ST STE 2300</u>	
City: <u>DENVER</u>	State: <u>CO</u> Zip: <u>80202</u>

Contact Information:

Contact Name	Phone	Email	Comment
Merry, Jesse		<u>jmerry@billbarrettcorp.com</u>	
Axelson, Aaron	<u>(970) 876-1959</u>	<u>aaxelson@billbarrettcorp.com</u>	Production Foreman
Ghan, Scott	<u>(970) 876-1959</u>	<u>sghan@billbarrettcorp.com</u>	Environmental Health & Safety Coordinator

Compliance Summary:

QtrQtr: <u>SWSW</u>	Sec: <u>21</u>	Twp: <u>6S</u>	Range: <u>91W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
<u>10/01/2010</u>	<u>200281621</u>	<u>PR</u>	<u>PR</u>	<u>S</u>			<u>N</u>

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
297253	WELL	PR	09/18/2009	GW	045-16357	GGU JOLLEY 13D-21-691	<input checked="" type="checkbox"/>
297270	WELL	PR	09/14/2009	GW	045-16370	GGU JOLLEY 13A-21-691	<input checked="" type="checkbox"/>
297271	WELL	PR	09/14/2009	GW	045-16371	GGU JOLLEY 13B-21-691	<input checked="" type="checkbox"/>
297272	WELL	PR	09/14/2009	GW	045-16372	GGU JOLLEY 13C-21-691	<input checked="" type="checkbox"/>
297273	WELL	PR	08/31/2009	GW	045-16373	GGU JOLLEY 14A-21-691	<input checked="" type="checkbox"/>
297274	WELL	PR	08/31/2009	GW	045-16374	GGU JOLLEY 14B-21-691	<input checked="" type="checkbox"/>
297275	WELL	PR	08/31/2009	GW	045-16375	GGU JOLLEY 14C-21-691	<input checked="" type="checkbox"/>
297276	WELL	PR	08/31/2009	GW	045-16376	GGU JOLLEY 14D-21-691	<input checked="" type="checkbox"/>
299802	WELL	PR	08/05/2009	GW	045-17749	GGU JOLLEY FEDERAL 21C-28-691	<input checked="" type="checkbox"/>
299803	WELL	PR	08/05/2009	GW	045-17750	GGU JOLLEY FEDERAL 21A-28-691	<input checked="" type="checkbox"/>
299804	WELL	PR	10/23/2009	LO	045-17751	GGU JOLLEY FEDERAL 21B-28-691	<input checked="" type="checkbox"/>
299805	WELL	PR	10/23/2009	LO	045-17752	GGU JOLLEY FEDERAL 21D-28-691	<input checked="" type="checkbox"/>
299806	WELL	PR	06/26/2009	GW	045-17753	GGU JOLLEY FEDERAL 11B-28-691	<input checked="" type="checkbox"/>

299807	WELL	PR	06/22/2009	GW	045-17754	GGU JOLLEY FEDERAL 11A-28-691	<input checked="" type="checkbox"/>
299808	WELL	PR	06/22/2009	GW	045-17755	GGU JOLLEY FEDERAL 11C-28-691	<input checked="" type="checkbox"/>
299809	WELL	PR	06/17/2009	GW	045-17756	GGU JOLLEY FEDERAL 11D-28-691	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
OTHER	Satisfactory	signs at separators		
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	stock paneling		
SEPARATOR	Satisfactory	4' welded-wire		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors		Satisfactory			
Emission Control Device	1	Satisfactory			
Horizontal Heated Separator	3	Satisfactory	3 quad unit		

Inspector Name: Baroumand, Soraya

Horizontal Heated Separator	2	Satisfactory	2 double unit		
-----------------------------	---	--------------	---------------	--	--

Tanks/Berms: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	6	500 BBLS	HEATED STEEL AST	,

S/U/V: Satisfactory Comment: 3 heated w/ECBs & bird cones. 3 non-heated

Corrective Action: _____ Corrective Date: _____

Paint

Condition Adequate

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335526

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 297253 API Number: 045-16357 Status: PR Insp. Status: PR

Facility ID: 297270 API Number: 045-16370 Status: PR Insp. Status: PR

Facility ID: 297271 API Number: 045-16371 Status: PR Insp. Status: PR

Facility ID: 297272 API Number: 045-16372 Status: PR Insp. Status: PR

Facility ID: 297273 API Number: 045-16373 Status: PR Insp. Status: PR

Facility ID: 297274 API Number: 045-16374 Status: PR Insp. Status: PR

Facility ID: 297275 API Number: 045-16375 Status: PR Insp. Status: PR

Facility ID: 297276 API Number: 045-16376 Status: PR Insp. Status: PR

Facility ID: 299802 API Number: 045-17749 Status: PR Insp. Status: PR

Facility ID: <u>299803</u>	API Number: <u>045-17750</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299804</u>	API Number: <u>045-17751</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299805</u>	API Number: <u>045-17752</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299806</u>	API Number: <u>045-17753</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299807</u>	API Number: <u>045-17754</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299808</u>	API Number: <u>045-17755</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>299809</u>	API Number: <u>045-17756</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y

Comment: _____
 Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? Pass
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment:

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Berms	Pass					

Inspector Name: Baroumand, Soraya

Ditches	Pass					
S/U/V: Satisfactory		Corrective Date: _____				
Comment: _____						
CA: _____						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
659700059	INSPECTION APPROVED	http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2865377