

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

02/03/2012

Document Number:

663800121

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier: 210726 Facility ID: 322530 Loc ID:                      Tracking Type:                      Inspector Name: LONGWORTH, MIKE

**Operator Information:**OGCC Operator Number: 10318 Name of Operator: VAQUERO ENERGY INCAddress: 5060 CALIFORNIA AVE STE 640City: BAKERSFIELD State: CA Zip: 93309**Contact Information:**

| Contact Name    | Phone | Email                            | Comment |
|-----------------|-------|----------------------------------|---------|
| Coutts, Brandon |       | brandon.coutts@vaqueroenergy.com |         |
| ANDREWS, DAVID  |       | david.andrews@state.co.us        |         |

**Compliance Summary:**QtrQtr: SWNW Sec: 14 Twp: 6S Range: 94W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 05/16/2000 | 200007593 | ID         | TA          | S                            |          | P              | N               |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name                   |                                     |
|-------------|----------|--------|-------------|------------|-----------|---------------------------------|-------------------------------------|
| 210726      | WELL     | PR     | 12/07/2011  | GW         | 045-06484 | WF CLOUGH FEDERAL 14-12-6S-94W  | <input checked="" type="checkbox"/> |
| 322530      | LOCATION | AC     | 04/14/2009  |            | -         | WF CLOUGH FEDERAL-66S94W 14SWNW | <input type="checkbox"/>            |

**Equipment:**Location Inventory

Special Purpose Pits:                      Drilling Pits:                      Wells:                      Production Pits:                       
 Condensate Tanks:                      Water Tanks:                      Separators:                      Electric Motors:                       
 Gas or Diesel Motors:                      Cavity Pumps:                      LACT Unit:                      Pump Jacks:                       
 Electric Generators:                      Gas Pipeline:                      Oil Pipeline:                      Water Pipeline:                       
 Gas Compressors:                      VOC Combustor:                      Oil Tanks:                      Dehydrator Units:                       
 Multi-Well Pits:                      Pigging Station:                      Flare:                      Fuel Tanks:                     

**Location****Lease Road:**

| Type   | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory                |         |                   |      |

| <b>Signs/Marker:</b> |                             |                                     |                                         |            |
|----------------------|-----------------------------|-------------------------------------|-----------------------------------------|------------|
| Type                 | Satisfactory/Unsatisfactory | Comment                             | Corrective Action                       | CA Date    |
| WELLHEAD             | Satisfactory                |                                     |                                         |            |
| CONTAINERS           | Unsatisfactory              | 55 gallon drum buried by gas lines. | Install sign to comply with rule 210.b. | 02/17/2012 |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: 1-888-538-9262

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                             |                         |                       |            |
|---------------------------|-----------------------------|-------------------------|-----------------------|------------|
| Type                      | Satisfactory/Unsatisfactory | Comment                 | Corrective Action     | CA Date    |
| WEEDS                     | Unsatisfactory              | weeds covering location | Cut and control weeds | 03/26/2012 |

| <b>Spills:</b>                                         |      |        |                   |         |
|--------------------------------------------------------|------|--------|-------------------|---------|
| Type                                                   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Equipment:</b>  |   |                             |         |                   |         |
|--------------------|---|-----------------------------|---------|-------------------|---------|
| Type               | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Gathering Line     |   | Satisfactory                |         |                   |         |
| Deadman # & Marked | 2 | Satisfactory                |         |                   |         |

| <b>Venting:</b> |         |  |  |
|-----------------|---------|--|--|
| Yes/No          | Comment |  |  |
| NO              |         |  |  |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 322530

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 210726 API Number: 045-06484 Status: PR Insp. Status: PR

**BradenHead**

Comment: Braden is tied into production

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION****Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

**Non-Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Inspector Name: LONGWORTH, MIKE

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_