



**RECEIVED**  
2/3/2012

**SUNDRY NOTICE**

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b)

1. OGCC Operator Number: <b>96850</b>	4. Contact Name <b>Karolina Blaney</b>	Complete the Attachment Checklist OP OGCC
2. Name of Operator: <b>WPX Energy Rocky Mountain, LLC</b>	Phone: <b>970 683 2295</b>	
3. Address: <b>1058 County Road 215</b> City: <b>Parachute</b> State: <b>CO</b> Zip: <b>81635</b>	Fax: <b>970 285 9573</b>	
5. API Number <b>05-045-19560</b>	OGCC Facility ID Number <b>417582</b>	Survey Plat
6. Well/Facility Name:	7. Well/Facility Number <b>RWF 13-31</b>	Directional Survey
8. Location (Qtr/Qt, Sec, Twp, Rng, Meridian): <b>NWSW-531-6S-94W-6 M</b>		Surface Eqpm Diagram
9. County: <b>Garfield</b>	10. Field Name: <b>Rulison</b>	Technical Info Page <input checked="" type="checkbox"/>
11. Federal, Indian or State Lease Number:		Other <input checked="" type="checkbox"/>

**General Notice**

**CHANGE OF LOCATION:** Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)

Change of <b>Surface</b> Footage from Exterior Section Lines:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Change of <b>Surface</b> Footage to Exterior Section Lines:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Change of <b>Bottomhole</b> Footage from Exterior Section Lines:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Change of <b>Bottomhole</b> Footage to Exterior Section Lines:	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bottomhole location Qtr/Qt, Sec, Twp, Rng, Mer  
 Latitude \_\_\_\_\_ Distance to nearest property line \_\_\_\_\_ Distance to nearest bldg, public rd, utility or RR \_\_\_\_\_  
 Longitude \_\_\_\_\_ Distance to nearest lease line \_\_\_\_\_ Is location in a High Density Area (rule 603b)? Yes/No \_\_\_\_\_  
 Ground Elevation \_\_\_\_\_ Distance to nearest well same formation \_\_\_\_\_ Surface owner consultation date: \_\_\_\_\_

GPS DATA:  
 Date of Measurement \_\_\_\_\_ PDOP Reading \_\_\_\_\_ Instrument Operator's Name \_\_\_\_\_

**CHANGE SPACING UNIT**

Formation	Formation Code	Spacing order number	Unit Acreage	Unit configuration

Remove from surface bond  
 Signed surface use agreement attached

**CHANGE OF OPERATOR** (prior to drilling):  
 Effective Date: \_\_\_\_\_  
 Plugging Bond:  Blanket  Individual

**CHANGE WELL NAME** NUMBER  
 From: \_\_\_\_\_  
 To: \_\_\_\_\_  
 Effective Date: \_\_\_\_\_

**ABANDONED LOCATION:**  
 Was location ever built?  Yes  No  
 Is site ready for inspection?  Yes  No  
 Date Ready for inspection: \_\_\_\_\_

**NOTICE OF CONTINUED SHUT IN STATUS**  
 Date well shut in or temporarily abandoned: \_\_\_\_\_  
 Has Production Equipment been removed from site?  Yes  No  
 MIT required if shut in longer than two years. Date of last MIT \_\_\_\_\_

**SPUD DATE:** \_\_\_\_\_  **REQUEST FOR CONFIDENTIAL STATUS** (6 mos from date casing set)

**SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK** \*submit cbl and cement job summaries

Method used	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom	Date

**RECLAMATION:** Attach technical page describing final reclamation procedures per Rule 1004.  
 Final reclamation will commence on approximately \_\_\_\_\_  Final reclamation is completed and site is ready for inspection.

**Technical Engineering/Environmental Notice**

Notice of Intent Approximate Start Date: \_\_\_\_\_  Report of Work Done Date Work Completed: \_\_\_\_\_

Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)

<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Disposal
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested	<input type="checkbox"/> Status Update/Change of Remediation Plans
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: <b>Background</b>	for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Karolina Blaney Date: 2/3/2012 Email: Karolina.Blaney@Williams.com  
 Print Name: Karolina Blaney Title: Environmental Specialist

COGCC Approved: [Signature] Title: FOR Date: 02/08/2012  
 CONDITIONS OF APPROVAL, IF ANY: Chris Carfield  
EPS NW Region

**TECHNICAL INFORMATION PAGE**



FOR OGCC USE ONLY

1. OGCC Operator Number: _____	API Number: _____
2. Name of Operator: _____	OGCC Facility ID # _____
3. Well/Facility Name: _____	Well/Facility Number: _____
4. Location (QtrQtr, Sec, Twp, Rng, Meridian): _____	

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. **DESCRIBE PROPOSED OR COMPLETED OPERATIONS**



**Legend**

- Sample Location
- Existing Road
- Existing Pad  
Limit of Disturbance

**RWF 13-31  
Arsenic Background Sample Location Map  
T6S R94W, Section 31**

**January 30, 2012**





**YOUR LAB OF CHOICE**

12065 Lebanon Rd.  
 Mt. Juliet, TN 37122  
 (615) 758-5858  
 1-800-767-5859  
 Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
 WPX Energy  
 1058 County Road 215  
 Parachute, CO 81635

Date Received : January 21, 2012  
 Description : RWF13-31  
 Sample ID : RWF13-31  
 Collected By : MA  
 Collection Date : 01/20/12 09:58

ESC Sample # : L556891-01  
 Site ID : RWF13-31  
 Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Chromium,Hexavalent	BDL	2.0	mg/kg	3060A/7196A	01/26/12	1
Chromium,Trivalent	17.	2.0	mg/kg	Calc.	01/25/12	1
ORP	130		mV	2580	01/24/12	1
pH	8.7		su	9045D	01/24/12	1
Sodium Adsorption Ratio	13.			Calc.	01/23/12	1
Specific Conductance	640		umhos/cm	9050AMod	01/26/12	1
Mercury	0.034	0.020	mg/kg	7471	01/23/12	1
Arsenic	5.5	1.0	mg/kg	6010B	01/25/12	1
Barium	5600	0.25	mg/kg	6010B	01/25/12	1
Cadmium	BDL	0.25	mg/kg	6010B	01/25/12	1
Chromium	17.	0.50	mg/kg	6010B	01/25/12	1
Copper	14.	1.0	mg/kg	6010B	01/25/12	1
Lead	10.	0.25	mg/kg	6010B	01/25/12	1
Nickel	16.	1.0	mg/kg	6010B	01/25/12	1
Selenium	BDL	1.0	mg/kg	6010B	01/25/12	1
Silver	1.2	0.50	mg/kg	6010B	01/25/12	1
Zinc	48.	1.5	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35  
 L556891-01 (PH) - 8.7@21.2c



**YOUR LAB OF CHOICE**

12065 Lebanon Rd.  
Mt. Juliet, TN 37122  
(615) 758-5858  
1-800-767-5859  
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
WPX Energy  
1058 County Road 215  
Parachute, CO 81635

Date Received : January 21, 2012  
Description : RWF13-31  
Sample ID : RWF13-31-B-1  
Collected By : MA  
Collection Date : 01/20/12 10:12

ESC Sample # : L556891-03

Site ID : RWF13-31

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	5.8	1.0	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35



YOUR LAB OF CHOICE

12065 Lebanon Rd.  
Mt. Juliet, TN 37122  
(615) 758-5858  
1-800-767-5859  
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
WPX Energy  
1058 County Road 215  
Parachute, CO 81635

Date Received : January 21, 2012  
Description : RWF13-31  
Sample ID : RWF13-31-B-2  
Collected By : MA  
Collection Date : 01/20/12 10:21

ESC Sample # : L556891-04  
Site ID : RWF13-31  
Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	4.8	1.0	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35



YOUR LAB OF CHOICE

12065 Lebanon Rd.  
Mt. Juliet, TN 37122  
(615) 758-5858  
1-800-767-5859  
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
WPX Energy  
1058 County Road 215  
Parachute, CO 81635

Date Received : January 21, 2012  
Description : RWF13-31  
Sample ID : RWF13-31-B-3  
Collected By : MA  
Collection Date : 01/20/12 10:28

ESC Sample # : L556891-05  
Site ID : RWF13-31  
Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	4.3	1.0	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35



YOUR LAB OF CHOICE

12065 Lebanon Rd.  
Mt. Juliet, TN 37122  
(615) 758-5858  
1-800-767-5859  
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
WPX Energy  
1058 County Road 215  
Parachute, CO 81635

Date Received : January 21, 2012  
Description : RWF13-31  
Sample ID : RWF13-31-B-4  
Collected By : MA  
Collection Date : 01/20/12 10:35

ESC Sample # : L556891-06  
Site ID : RWF13-31  
Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	5.6	1.0	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35



YOUR LAB OF CHOICE

12065 Lebanon Rd.  
Mt. Juliet, TN 37122  
(615) 758-5858  
1-800-767-5859  
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

January 27, 2012

Karolina Blaney  
WPX Energy  
1058 County Road 215  
Parachute, CO 81635

Date Received : January 21, 2012  
Description : RWF13-31  
Sample ID : RWF13-31-B-5  
Collected By : MA  
Collection Date : 01/20/12 10:46

ESC Sample # : L556891-07  
Site ID : RWF13-31  
Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	4.0	1.0	mg/kg	6010B	01/25/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 01/27/12 16:34 Printed: 01/27/12 16:35